



Commercial Vehicle Inspection Report

Decal Number: GJ96064
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21494119

Inspection Result:
PASS

K09-

FACILITY: STEELHEAD TRUCK AND TRAILER / S14810
INSPECTOR: SIDHU, GURVINDER / 300541
WORK ORDER #: 15829
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2025-Sep-11 12:40 PM PDT
INSP. COMPLETE: 2025-Sep-11 02:40 PM PDT

VEHICLE JUR: British Columbia
PLATE #: NS6311
LICENCED GVW(kg): 63500
VEHICLE YEAR: 2013
MAKE: WESTERN ST
MODEL:
REGI: 10633643
UNIT/FLEET#: 59
BODY STYLE: Truck Tractor
ODOMETER: 946053 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 5KJJAEDR2DPFD5840
OWNER/LESSEE NAME: BAYVIEW AUTO TOWING (2000) LTD, BAYVIEW AUTO TOWING (2000) LTD
ADDRESS: 201-155 176ST, 201-155 176ST
Surrey, British Columbia
V3S 9S4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED #1 AXLE BOTH SIDE LEAF SPRING BUSHINGS. REPLACED #3 AXLE R/H SHOCK.
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) REPLACED STEERING SHAFT UPPER U-JOINT.
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	36	36	5.6			6.4	✓
2	Clamp	30L	Automatic	38	38	7.1	6.4	6.4	7.9	
3	Clamp	30L	Automatic	38	38	4.8	4.8	4.8	4	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	60	40
2	75	88
3	90	92

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	14	14
Lining (Shoe)	13	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: SIDHU, GURVINDER

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-11 05:41 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

9/11/2025 5:41:47 PM PDT