



# Commercial Vehicle Inspection Report

Decal Number: GN22874  
 Decal Expiry Date: 2026-Oct-31  
 Inspection Number: 21730733

Inspection Result:  
**PASS**

<b>FACILITY:</b>	MT LEHMAN TRUCK AND TRAILER REPAIR LTD. / S20491	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2026-Apr-12 10 00 AM PDT
<b>INSPECTOR:</b>	OTAL, AMINDER SINGH / 202239	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2026-Apr-12 11 30 AM PDT
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Semi-annual		
<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	13727440	<b>VIN:</b>	1FUJH#DR0NLNB6100
<b>PLATE #:</b>	91853P	<b>UNIT/FLEET#:</b>		<b>OWNER/LESSEE NAME:</b>	TPINE LEASING CAPITAL CORP, TPINE LEASING CAPITAL CORP
<b>LICENCED GVW(kg):</b>	46500	<b>BODY STYLE:</b>	Truck Tractor	<b>ADDRESS:</b>	401-1450 MEGARSIDE DR
<b>VEHICLE YEAR:</b>	2022	<b>ODOMETER:</b>	782235 KM		MISSISSAUGA, Ontario
<b>MAKE:</b>	FREIGHTLIN	<b>HUB ODOMETER:</b>			LST2N5, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Result
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) MUFFLER BACKSIDE PIPE REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) XL2 B/S SLACK REPLACED
Section 3H - Hydraulic Brakes	Repaired (same day) AIR LINES SECURED
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Not Applicable
Section 7 - Electrical System	Repaired (same day) HEADLIGHT REPLACED
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	5			7	✓
2	Clamp	30L	Automatic	34	34	5	4	5	5	
3	Clamp	30L	Automatic	34	34	9	8	5	8	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0	Pad	12	12	Drum		
2	40	42	Lining (Shoe)	18	18	Drum		
3	55	74	Lining (Shoe)	16	13	Drum		

**Inspection Comments:**  
 Has this Vehicle been road tested? No  
 Inspector: OTAL, AMINDER SINGH  
 Road Test Date: \_\_\_\_\_  
 Signature:   
 Road Tester: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2026-Apr-12 06 45 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE RE: THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**  
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement  
 CVSE014  
 4/12/2026 6:46:58 PM PDT