

FACILITY:	COCA-COLA CANADA BOTTLING / P0263	INSP. TYPE:	Complete	INSP. START:	2025-Oct-15 09:30 AM PDT
INSPECTOR:	Gonzales, Homar / 200115	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Oct-15 11:00 AM PDT
WORK ORDER #:	614074058	INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	06776861	VIN:	2XKHAM7A3AM263579
PLATE #:	RY4856	UNIT/FLEET#:	09B998009	OWNER/LESSEE NAME:	COCA-COLA CANADA BOTTLING, COCA-COLA CANADA BOTTLING
UNWEIGHTED GVW(kg):	31600	BODY STYLE:	Truck Tractor	ADDRESS:	Unit 110, 8040 Zylmans Way, Unit 110, 8040 Zylmans Way
VEHICLE YEAR:	2010	ODOMETER:	249070 KM		Richmond, British Columbia
MAKE:	KENWORTH	HUB ODOMETER:			V6W 0C3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	40	40	14			14	✓
2	Clamp	30	Automatic	40	40	13	13	13	12	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	30	35	Lining (Shoe)	18	18	Drum	0.00	0.00
2	30	30	Lining (Shoe)	19	19	Drum	0.00	0.00
Comment:			Comment:			Comment: brake drum did not remove		

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____

Inspector: Gonzales, Homar **Signature:** 

This Inspection Report was submitted to CVSE on 2025-Oct-15 11:42 AMPDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.