



# Commercial Vehicle Inspection Report

Decal Number: PY09264  
 Decal Expiry Date: 2027-Jan-31  
 Inspection Number: 21644421

Inspection Result:  
**PASS**

**FACILITY:** COCA-COLA CANADA BOTTLING / P0263    **INSP. TYPE:** Complete    **INSP. START:** 2026-Jan-27 02:15 PM PST  
**INSPECTOR:** GREWAL, SUKHPREET / 301637    **INSP. CLASS:** Class 3 - Trailer and Semi-Trailer    **INSP. COMPLETE:** 2026-Jan-27 06:15 PM PST  
**WORK ORDER #:** 614196184    **INSP. REASON:** Annual

**VEHICLE JUR:** British Columbia    **REGI:** 09862306    **VIN:** 2M5931610B1123758  
**PLATE #:** 60333C    **UNIT/FLEET#:** 10T998494    **OWNER/LESSEE NAME:** Coca-Cola Canada Bottling Ltd., Coca-Cola Canada Bottling Ltd.  
**PERMITTED GVW(kg):** 999999    **BODY STYLE:** Van Trailer    **ADDRESS:** 8040 Zylmans Wy  
**VEHICLE YEAR:** 2011    **ODOMETER:**    **Richmond, British Columbia**  
**MAKE:** MANAC    **HUB ODOMETER:** 85375 KM    **V6W 0C3, Canada**  
**MODEL:** FT    **BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day)    Repaired Rear door seal
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30L	Automatic	38.1	38.1
2	Clamp	30L	Automatic	38.1	38.1
3	Clamp	30L	Automatic	38.1	38.1

**Comment:**

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
10	10	9	10	
14	14	14	14	
8	8	10	10	

**Comment:**

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	35	35
2	60	65
3	60	65

**Comment:**

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	19	19
Lining (Shoe)	16	16
Lining (Shoe)	15	15

**Comment:**

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

**Comment:** Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**  
 Has this Vehicle been road tested?  No    **Road Test Date:**    **Road Tester:**  
**Inspector:** GREWAL, SUKHPREET    **Signature:**

This Inspection Report was submitted to CVSE on 2026-Jan-27 06:16 PM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement