

BRITISH  
COLUMBIACommercial Vehicle  
Inspection ReportDecal Number: GH03179  
Decal Expiry Date: 2025-Aug-31  
Inspection Number: 21253352Inspection Result:  
**PASS**

KW1-1

FACILITY:	FLEETPRO MECHANICAL INC. / S20174	INSP. TYPE:	Complete	INSP. START:	2025-Feb-27 11:30 AM PST
INSPECTOR:	HANSRA, AKASHDEEP SINGH / 300342	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW. 5501 kg or more	INSP. COMPLETE:	2025-Feb-27 03:00 PM PST
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	03633510	VIN:	1NKDL40X06J991988
PLATE #:	WL6956	UNIT/FLEET#:	108	OWNER/LESSEE NAME:	CHAHAL, JAGDEEP, SINGH
LICENCED GVW(kg):	44000	BODY STYLE:	Dump Truck	ADDRESS:	6033 181A ST. Surrey, British Columbia V3S 4M1, Canada
VEHICLE YEAR:	2006	ODOMETER:	869890 KM		
MAKE:	KENWORTH	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Repaired (same day) CHANGED EXHAUST CLAMP UNDER CAB, CHANGED ENGINE FRONT MOUNTS
<b>Section 2 - Suspension</b>	Repaired (same day) TIGHTENED XL-2 AND 3 P/S SHOCK MOUNTING BOLTS
<b>Section 3 - Brake System</b>	Passed
<b>Section 3A - Air Brakes</b>	Repaired (same day) SECURE AIR HOSES ON XL-3
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Passed
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Repaired (same day) CHANGED WIND SHIELD
<b>Section 9A - Tires</b>	Passed
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering	
1	Clamp	24	Automatic	34	34	15			15		
2	Clamp	30	Automatic	40	40	14	13	12	14		
3	Clamp	30	Automatic	40	40	9	11	9	11		

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	40	Lining (Shoe)	13	13	Drum		
2	75	70	Lining (Shoe)	14	14	Drum		
3	65	65	Lining (Shoe)	14	14	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**

Has this Vehicle been road tested? No Road Test Date: 2025-Feb-27 Road Tester: HANSRA, AKASHDEEP SINGH  
 Inspector: HANSRA, AKASHDEEP SINGH Signature: HANSRA, AKASHDEEP SINGH

This Inspection Report was submitted to CVSE on 2025-Feb-28 03:44 PM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

2/28/2025 3:44:37 PM PST