



BRITISH  
COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GL05833  
Decal Expiry Date: 2026-Mar-31  
Inspection Number: 21508795

Inspection Result:

**PASS**

FACILITY: OCEAN TIRE SERVICE LTD. / S20280  
INSPECTOR: RAI, SARABDEEP SINGH / 202959  
WORK ORDER #:  
VEHICLE JUR: British Columbia  
PLATE #: WM0718  
LICENSED GVW(kg): 47000  
VEHICLE YEAR: 2013  
MAKE: MACK  
MODEL:  
INSP. TYPE: Complete  
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
INSP. REASON: Semi-annual  
INSP. START: 2025-Sep-23 06:00 PM PDT  
INSP. COMPLETE: 2025-Sep-23 08:00 PM PDT  
REGI: 10676208  
UNIT/FLEET#: 102  
BODY STYLE: Truck Tractor  
ODOMETER: 491383 KM  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 1M1AW07Y6DM033047  
OWNER/LESSEE NAME: GDR LOGISTICS, INC.  
ADDRESS: 9-3051 CROSSLEY DR  
Abbotsford, British Columbia  
V2T5R4, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) AXLE 1 BOTH SIDE TIE ROD END REPLACED , AXLE 1 RIGHT SIDE SHOCK
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AIR LINE SECURED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) MARKER LIGHT FIXED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) L/S STEP LOOSEN AND CAB LEVELING VALVE REPLACED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Mr Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	36	34
2	Clamp	30	Automatic	36	34
3	Clamp	30	Automatic	35	35

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8			8	✓
20	20	20	20	
20	20	20	20	

Comment:

## Mr Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	75	65
2	55	45
3	75	55

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	16
Lining (Shoe)	16	17
Lining (Shoe)	13	16

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment: 0

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: RAI, SARABDEEP SINGH

Road Test Date:  
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-24 03:44 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSED014

1/24/2025 3:44:28 PM PDT

