



# Commercial Vehicle Inspection Report

Decal Number: **GM12042**  
Decal Expiry Date: **2026-Jul-31**  
Inspection Number: **21638134**

112-1

Inspection Result:  
**PASS**

**FACILITY:** PETERBILT PACIFIC INC. / S12550 **INSP. TYPE:** Complete **INSP. START:** 2026-Jan-19 09:00 AM PST  
**INSPECTOR:** Harris, Derek Christopher / 201642 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW **INSP. COMPLETE:** 2026-Jan-21 10:00 PM PST  
**WORK ORDER #:** AB146427 **INSP. REASON:** Semi-annual

**VEHICLE JUR:** British Columbia **REGI:** 12758558 **VIN:** 1XPXD49X1KD617069  
**PLATE #:** XC1480 **UNIT/FLEET#:** 389 **OWNER/LESSEE NAME:** JONATHAN ORANGO VENTURES LIMITED, JONATHAN ORANGO VENTURES LIMITED  
**PERMITTED GVW(kg):** 37000 **BODY STYLE:** Truck Tractor **ADDRESS:** 41330 DYKE RD  
**VEHICLE YEAR:** 2019 **ODOMETER:** 1165257 KM **DEROCHA:** Derocha, British Columbia  
**MAKE:** PETERBILT **HUB ODOMETER:** **VON1G0:** Canada  
**MODEL:** **BRAKE TYPE:** Air **FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) -PASSENGER SIDE SPRING PINS REPLACED -#2 AXLE DRIVER SIDE AIR BAG REPLACED
Section 3 - Brake System	Repaired (same day) -STEER AXLE BRAKES REPLACED
Section 3A - Air Brakes	Repaired (same day) -#2 AXLE PASSENGER SIDE BRAKE POT REPLACED
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) -REPLACED DRIVER SIDE HEADLIGHT MARKER BULBS - REPLACED LICENSE PLATE LIGHT
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day) REPLACED/REPAIRED AS REQUIRED
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	36	36	7			2	✓
2	Clamp	30L	Automatic	44	44	5	5	6	6	
3	Clamp	30L	Automatic	44	44	5	5	5	5	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	38	33	Lining (Shoe)	19	19	Drum		
2	77	35	Lining (Shoe)	15	19	Drum		
3	33	95	Lining (Shoe)	18	14	Drum		

**Inspection Comments:**  
Has this Vehicle been road tested?  No **Road Test Date:**   
**Inspector:** Harris, Derek Christopher **Signature:**  **Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Jan-21 10:11 PMPST  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.