



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GN22809
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21713715

Inspection Result:

PASS

FACILITY:	MT. LEHMAN TRUCK AND TRAILER REPAIR LTD. / S20491	INSP. TYPE:	Complete	INSP. START:	2026-Mar-29 10:30 AM PDT
INSPECTOR:	OTAL, AMNINDER SINGH / 202239	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Mar-29 12:00 PM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11433527	VIN:	4V4NC9EJ09N270773
PLATE #:	93658P	UNIT/FLEET#:	145	OWNER/LESSEE NAME:	XPS TRUCKING INC, XPS TRUCKING INC
LICENCED GVW(kg):	47000	BODY STYLE:	Truck Tractor	ADDRESS:	6229 256 ST Abbotsford, British Columbia
VEHICLE YEAR:	2009	ODOMETER:	1662814 KM		V4W1K2, Canada
MAKE:	VOLVO	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	32	32
2	Clamp	30	Automatic	34	34
3	Clamp	30	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11			10	✓
9	8	8	10	
13	12	12	12	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	74	72
2	84	75
3	84	85

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	13	14
Lining (Shoe)	13	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: OTAL, AMNINDER SINGH

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Mar-29 02:55 PMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

3/29/2026 2:55:30 PM PDT