



Commercial Vehicle Inspection Report

Decal Number: GN06368
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21787113

Inspection Result:
PASS

LI

FACILITY: VANKO SERVICES LTD / S11470 **INSP. TYPE:** Complete **INSP. START:** 2026-May-21 07:43 AM PDT
INSPECTOR: VANDER KOOL, JESSE JACOB / 202990 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-May-27 08:43 AM PDT
WORK ORDER #: 7314 **INSP. REASON:** Semi-annual

VEHICLE JUR: British Columbia **REGI:** 01905560 **VIN:** 2FZHAZCV84AM45045
PLATE #: A3H6G2 **UNIT/FLEET#:** **OWNER/LESSEE NAME:** TIMBERLINE SOLUTIONS, TIMBERLINE
LICENCED GWV(kg): 26100 **BODY STYLE:** Truck Tractor **ADDRESS:** PO BOX 532, PO BOX 532
VEHICLE YEAR: 2004 **ODOMETER:** 1028687 KM Salmon Arm, British Columbia
MAKE: STERLING **HUB ODOMETER:** V1E 4N6, Canada
MODEL: **BRAKE TYPE:** Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACE SUSPENTION CUSHION ON DRIVER SIDE
Section 3 - Brake System	Repaired (same day) REPLACE BRAKE POT BASS ON #1L AND HOSE
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	34	34	12			14	✓
2	Clamp	30	Automatic	36	36	18	18	18	18	
3	Clamp	30	Automatic	36	36	20	20	20	20	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	80	30	Lining (Shoe)	11	20	Drum		
2	80	90	Lining (Shoe)	13	11	Drum		
3	30	30	Lining (Shoe)	20	20	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**
Inspector: VANDER KOOL, JESSE JACOB **Signature:** 

This Inspection Report was submitted to CVSE on 2026-May-27 08:44 AMPDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.