



Commercial Vehicle Inspection Report

Decal Number: GN35735
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21782185

118
Inspection Result
PASS

ACILITY: SANDHER TRUCK & TRAILER REPAIR LTD. / S15370
INSPECTOR: SANDHU, SIMRANJEET / 300113
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-May-22 02:30 PM PDT
INSP. COMPLETE: 2026-May-22 04:30 PM PDT

VEHICLE JUR: British Columbia
LATE #: XD0525
LICENCED GVW(kg): 47000
VEHICLE YEAR: 2012
MAKE: VOLVO
MODEL:
REGI: 10493620
UNIT/FLEET#: 202
BODY STYLE: Truck Tractor
ODOMETER: 1379288 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 4V4NC9KK6CN554770
OWNER/LESSEE NAME: GSTAR, TRUCKING LTD
ADDRESS: 15071 76A AVE
Surrey, British Columbia
V3S5P1, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	32	33	11.9			11.9	✓
2	Clamp	30	Automatic	36	35	10.3	10.3	10.3	11.1	
3	Clamp	30	Automatic	34	35	11.1	10.3	10.3	9.5	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	65	70	Lining (Shoe)	15	14	Drum		
2	45	55	Lining (Shoe)	19	17	Drum		
3	40	60	Lining (Shoe)	20	16	Drum		

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: SANDHU, SIMRANJEET
Road Test Date: [Signature]
Road Tester: [Signature]

This Inspection Report was submitted to CVSE on 2026 May-22 04:50 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.