



# Commercial Vehicle Inspection Report

Decal Number: GM00108  
 Decal Expiry Date: 2026-Jul-31  
 Inspection Number: 21639731

1103-3  
 Inspection Result:  
**PASS**

**FACILITY:** SALMON ARM AUTO & TRUCK / S17050  
**INSPECTOR:** DROLET, PAUL BERNARD / 201030  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Semi-annual

**INSP. START:** 2026-Jan-23 08:05 AM PST  
**INSP. COMPLETE:** 2026-Jan-23 10:00 AM PST

**VEHICLE JUR:** British Columbia  
**REGI:** 12799930  
**VIN:** 3HCDZAPR4KL233700  
**PLATE #:**  
**UNIT/FLEET#:** 1325  
**OWNER/LESSEE NAME:** ACE Courier Service, ACE Courier Service  
**PERMITTED GVW(kg):** 39500  
**BODY STYLE:** Truck Tractor  
**ADDRESS:** 760 Crowley Ave, 760 Crowley Ave  
**VEHICLE YEAR:** 2019  
**ODOMETER:** 898770 KM  
**Kelowna, British Columbia**  
**MAKE:** INTERNATNA  
**HUB ODOMETER:**  
**V1Y 7G7, Canada**  
**MODEL:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Replace #3 left drum and shoes
Section 3A - Air Brakes	Repaired (same day) tightened loose #2 axle spring brake quick release valve fitting (leaking)
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) Replace damaged fire extinguisher
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	30	30
2	Clamp	30L	Automatic	30	30
3	Clamp	30L	Automatic	30	35

Comment: Replaced left #3 drum and shoes

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
11			14	✓
13	12	11	14	
11	12	11	11	

Comment:

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	30	45
2	75	80
3	125	45

Comment:

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	20	20
Lining (Shoe)	15	14
Lining (Shoe)	10	18

Comment: #3 left replaced

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. #3 left replaced

**Inspection Comments:**

Has this Vehicle been road tested? Yes  
 Inspector: DROLET, PAUL BERNARD  
 Road Test Date: Before Inspection  
 Road Tester: Paul Drolet  
 Signature: *Paul Drolet*

This Inspection Report was submitted to CVSE on 2026-Jan-23 10:37 AM PST  
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement