



Commercial Vehicle Inspection Report

Decal Number: **GM09709**
 Decal Expiry Date: **2027-Feb-28**
 Inspection Number: **21658780**

M12-2
 Inspection Result:
PASS

FACILITY: Inland Truck & Equipment Ltd / S20218
INSPECTOR: Broughton, Tyler Glen / 114431
WORK ORDER #: 14017QNS

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual

INSP. START: 2026-Feb-05 08:03 AM PST
INSP. COMPLETE: 2026-Feb-09 12:03 PM PST

VEHICLE JUR: British Columbia
PLATE #: G98260

REGI: 13712403
UNIT/FLEET#:

VIN: 1M1AA18Y81W137042
OWNER/LESSEE NAME: RAMBULL RANCH AND TRANSPORT, RAMBULL RANCH
ADDRESS: 5176 BAKER KERSLEY RD, Quesnel, British Columbia V2J6L6, Canada

LICENCED GVW(kg): 47000
VEHICLE YEAR: 2001
MAKE: MACK
MODEL:

BODY STYLE: Truck Tractor
ODOMETER: 572870 KM
HUB ODOMETER: 99 KM
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Result
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) power steering line leak
Section 3 - Brake System	Repaired (same day) left front diff suspension bushing worn out
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Repaired (same day) left steer brake drum over rotation
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) kingpins have excessive up and down play
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	26	25	10			10	✓
2	Clamp	30	Automatic	33	30	17	17	19	16	
3	Clamp	30	Automatic	36	33	13	13	15	15	

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	80	Lining (Shoe)	21	13	Drum		
2	60	80	Lining (Shoe)	14	12	Drum		
3	75	30	Lining (Shoe)	16	18	Drum		

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: Broughton, Tyler Glen **Signature:**

This Inspection Report was submitted to CVSE on 2026-Feb-09 12:03 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE014
 2/9/2026 12:03:47 PM PST