



Commercial Vehicle Inspection Report

Decal Number: GM19129
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21620986

M13-1
Inspection Result:
PASS

ACTIVITY: J & G FLEET SERVICES LTD / S16741
INSPECTOR: STEFFEN, HANS MARTIN / 100332
WORK ORDER #: 21606
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Jan-06 10:30 AM PST
INSP. COMPLETE: 2026-Jan-06 12:30 PM PST

VEHICLE JUR: British Columbia
LATE #: 56401C
PERMITTED GVW(kg): 999999
VEHICLE YEAR: 2004
MAKE: MIDLAND
MODEL: PONY
REGI: 03584432
UNIT/FLEET#: TLPONY-01
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2MFA2R8C64R002777
OWNER/LESSEE NAME: TIMBRO CONTRACTING LTD, TIMBRO
ADDRESS: 7357 PIONEER AVE PO BOX 95, 7357 PIONEER AVE PO BOX 95 Agassiz, British Columbia V0M1A0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)					Tire Tread Depth (mm)					
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	44	44	10	6	9	8	
2	Clamp	30	Automatic	44	44	12	12	5	4	
Comment:					Comment:					

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	90	Lining (Shoe)	18	12	Drum		
2	75	75	Lining (Shoe)	15	15	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this vehicle been road tested? No
Inspector: STEFFEN, HANS MARTIN
Road Test Date: *Hans Steffen*
Signature: *Hans Steffen*
Road Tester:

This inspection report was submitted to CVSE on 2026-Jan-06 02:17 PM PST
The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.