



# Commercial Vehicle Inspection Report

Decal Number: FY27918  
 Decal Expiry Date: 2023-Dec-31  
 Inspection Number: 20569172

M14-5

Inspection Result:  
**PASS**

**FACILITY:** MODERN DIESEL TRUCK REPAIR LTD. / S15400  
**INSPECTOR:** Cheema, Ballej Singh / 203156  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Semi-annual

**INSP. START:** 2023-Jun-30 04:20 PM PDT  
**INSP. COMPLETE:** 2023-Jun-30 05:20 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 9Q4Q1C  
**LICENCED GVW(kg):** 43100  
**VEHICLE YEAR:** 2005  
**MAKE:** STERLING  
**MODEL:**

**REGI:** 03251500  
**UNIT/FLEET#:**  
**BODY STYLE:** Dump Truck  
**ODOMETER:** 967283 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:** Diesel

**VIN:** 2FZHAZCV55AU76612  
**OWNER/LESSEE NAME:** LTD, 1243245 B.C  
**ADDRESS:** 311-3381 CAMBIE ST  
 Vancouver, British Columbia  
 V5Z4R3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) RIGHT SIDE DRAG LINK ARM REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AIR LEAK FIX
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) ALL LIGHTS REPAIR
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIR BOX
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

### Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	33	32
2	Clamp	30	Automatic	33	33
3	Clamp	30	Automatic	34	33

### Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	10.3			11.9	✓
		13.5	14.3	13.5	
	15.9	15.9	15.9	15.9	

Comment:

Comment:

### Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	72	74
2	54	48
3	57	59

### Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	16	17
Lining (Shoe)	16	16

### Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Comment:

Comment:

### Inspection Comments:

Has this Vehicle been road tested?  No  
 Inspector: Cheema, Ballej Singh

Road Test Date:  
 Signature: Ballej Singh

Road Tester:

This Inspection Report was submitted to CVSE on 2023-Jun-30 05:21 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

### NOTICE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE014

6/30/2023 5:21:55 PM PDT



# Commercial Vehicle Inspection Report

Decal Number: FY27918  
Decal Expiry Date: 2023-Dec-31  
Inspection Number: 20569172

M14-3

Inspection Result:  
**PASS**

**FACILITY:** MODERN DIESEL TRUCK REPAIR LTD. / S15400  
**INSPECTOR:** Cheema, Baltej Singh / 203156  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Semi-annual

**INSP. START:** 2023-Jun-30 04:20 PM PDT  
**INSP. COMPLETE:** 2023-Jun-30 05:20 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 9Q4Q1C  
**LICENCED GVW(kg):** 43100  
**VEHICLE YEAR:** 2005  
**MAKE:** STERLING  
**MODEL:**

**REGI:** 03251500  
**UNIT/FLEET#:**  
**BODY STYLE:** Dump Truck  
**ODOMETER:** 967283 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:** Diesel

**VIN:** 2FZHACV55AU76612  
**OWNER/LESSEE NAME:** LTD, 1243245 B.C  
**ADDRESS:** 311-3381 CAMBIE ST  
 Vancouver, British Columbia  
 V5Z4R3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) RIGHT SIDE DRAG LINK ARM REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AIR LEAK FIX
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Repaired (same day) ALL LIGHTS REPAIR
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPAIR BOX
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

**Air Brake Chamber Type, Size and Push Rod Stroke (mm)**

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	33	32
2	Clamp	30	Automatic	33	33
3	Clamp	30	Automatic	34	33

Comment:

**Tire Tread Depth (mm)**

Outer L	Inner L	Inner R	Outer R	Steering
10.3			11.9	✓
13.5	13.5	14.3	13.5	
15.9	15.9	15.9	15.9	

Comment:

**Air Brake Camshaft Rotation (degrees)**

Axles	Left	Right
1	72	74
2	54	48
3	57	59

Comment:

**Brake Lining/Pad (mm)**

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	16	17
Lining (Shoe)	16	16

Comment:

**Rotor Thickness or Drum Inside Diameter (mm)**

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

**Inspection Comments:**

Has this Vehicle been road tested?  No  Yes  
**Inspector:** Cheema, Baltej Singh  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2023-Jun-30 05:21 PM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.