

M17-3
917



Commercial Vehicle Inspection Report

Decal Number: **CN91006**
 Decal Expiry Date: **2026-Nov-30**
 Inspection Number: **21787611**

Inspection Result:
PASS

FACILITY: HARKO HEAVY DUTY LTD. / S17130
INSPECTOR: KRANG, HAYDEN / 202186
WORK ORDER #: POWDER VENTURES PV-49
ORIGINAL INSP. #: 21787611

INSR. TYPE: Correction
INSR. CLASS: Class 3 - Trailer and Semi-Trailer
INSR. REASON: Semi-annual

INSR. START: 2026-May-25 05:13 PM PDT
INSR. COMPLETE: 2026-May-25 06:45 PM PDT

VEHICLE JUR.: British Columbia
REG.: 10468170
UNIT/FLEET: PV-49
VIN: 2MEB25HDY7R004398

PLATE #: [Blank]
OWNER/LESSEE NAME: POWDER VENTURES, LTD.
ADDRESS: 2576 MOUNTAIN VIEW DR
 Sun Peaks, British Columbia
 V0S0N0, Canada

LICENSED GVW(kg): 99999
VEHICLE YEAR: 2007
ODDMEETER: 0 KM
HUB ODDMEETER: [Blank]
MAKE: MIDLAND
MODEL: [Blank]
BRAKE TYPE: Air
FUEL TYPE: [Blank]

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	REPAIRED AIRLEAK ON APP.
Section 3A - Air Brakes	Repaired (same day)	REPLACED AXLE 2 BRAKES. REPLACED JR BRAKE.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPLACED RH AMBER MARKER.
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	37	8	7	7	6	
2	Clamp	30	Automatic	35	35	11	11	9	6	
3	Clamp	30	Automatic	37	35	11	10	7	7	

Comment: [Blank]

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Left	Right	Left	Right	Rotor/Drum	Left	Right
1	60	65	Lining (Shoe)	16	16	16	Drum		
2	25	25	Lining (Shoe)	19	19	19	Drum		
3	65	25	Lining (Shoe)	11	19	19	Drum		

Comment: [Blank]

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No
Inspector: KRANG, HAYDEN
Road Test Date: [Blank]
Signature:

This Inspection Report was submitted to CMVE on 2026-May-27 11:44 AM PDT.
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH YOUR REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Section 21 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the vehicle inspection programs and the Motor Vehicle Act. If you have any questions about the collection of this information, you may contact the Registrar, BCICMP at the Commercial Vehicle Safety Resources.
 6079926 11-04-27 AM PDT