



# Commercial Vehicle Inspection Report

Decal Number: GN34203  
Decal Expiry Date: 2027-Apr-30  
Inspection Number: 21726851

Inspection Result:  
**PASS**

No2

**FACILITY:** ACCELERATED MECHANICAL LTD. / S16580  
**INSPECTOR:** Harilstad, Milton John / 102798  
**WORK ORDER #:** 9605  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Annual  
**INSP. START:** 2026-Apr-08 06:07 PM PDT  
**INSP. COMPLETE:** 2026-Apr-08 07:07 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** G46754  
**REGI:** 10047044  
**UNIT/FLEET#:** 108  
**VIN:** 2AYNV6JV1A3S14255  
**OWNER/LESSEE NAME:** ROYAL BANK OF CANADA, RAINBOW GREENHOUSES INC RAINBOW GREENHOUSES INC  
**ADDRESS:** 43756 SOUTH SUMAS RD, 43756 SOUTH SUMAS RD Chilliwack, British Columbia V2R4L6, Canada

**LICENCED GVW(kg):** 14590  
**BODY STYLE:** Van  
**VEHICLE YEAR:** 2010  
**MAKE:** HINO  
**MODEL:**  
**ODOMETER:** 914289 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20	Automatic	35	35	8			10	✓
2	Clamp	30	Automatic	36	36	8	10	9	8	
<b>Comment:</b>						<b>Comment:</b>				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	40	40	Lining (Shoe)	16	16	Drum	0.00	0.00
2	45	45	Lining (Shoe)	15	15	Drum	0.00	0.00
<b>Comment:</b>			<b>Comment:</b>			<b>Comment:</b>		

**Inspection Comments:**  
 Has this Vehicle been road tested? No    Road Test Date: \_\_\_\_\_    Road Tester:  
**Inspector:** Harilstad, Milton John    **Signature:**

This Inspection Report was submitted to CVSE on 2026-Apr-09 09:08 AM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**  
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014  
 4/9/2026 9:08:55 AM PDT