



BRITISH COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GN39813  
Decal Expiry Date: 2026-Oct-31  
Inspection Number: 21727127

Inspection Result:  
**PASS**

N08-1

**FACILITY:** MODERN DIESEL TRUCK REPAIR LTD. / S15400  
**INSPECTOR:** KAMBOJ, RAJDEEP / 300155  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSP. REASON:** Semi-annual

**INSP. START:** 2026-Apr-08 04:25 PM PDT  
**INSP. COMPLETE:** 2026-Apr-08 06:30 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** 42034L  
**LICENCED GVW(kg):** 999999  
**VEHICLE YEAR:** 1993  
**MAKE:** MIDLAND  
**MODEL:** PONY

**REGI:** 08778418  
**UNIT/FLEET#:** tri  
**BODY STYLE:** Pup Trailer  
**ODOMETER:**  
**HUB ODOMETER:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

**VIN:** 2M9B2S6C1PR018679  
**OWNER/LESSEE NAME:** E2L CONSTRUCTION LTD, /  
**ADDRESS:** 234-2035 GLENAIRE DR  
 North Vancouver, British Columbia  
 V7P1Y2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WELDING DONE AT FEW SPOTS
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) 1XL RIGHT WHEEL SEAL REPLACED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	36	16.7	16.7	16.7	16.7	
2	Clamp	30	Automatic	38	34	15.9	16.7	16.7	16.7	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	60	Lining (Shoe)	17	17	Drum	420.62	420.75
2	60	50	Lining (Shoe)	17	19	Drum	420.75	420.37
Comment:			Comment:			Comment:		

**Inspection Comments:**

Has this Vehicle been road tested?  No  Yes  
**Inspector:** KAMBOJ, RAJDEEP  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Apr-09 10:54 AM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.