



Commercial Vehicle Inspection Report

Decal Number: GD25692
Decal Expiry Date: 2025-Aug-31
Inspection Number: 21037973

NK α α

Inspection Result:
PASS

FACILITY: TIP FLEET SERVICES CANADA LTD. / S7035
INSPECTOR: BLANCHARD, ROBERT BRENTON / 300461
WORK ORDER #: 436116

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2024-Aug-15 06:30 AM PDT
INSP. COMPLETE: 2024-Aug-15 08:30 AM PDT

VEHICLE JUR: Alberta
PLATE #:

REGI:
UNIT/FLEET#: QT2974

VIN: 1UYVS25348P484936
OWNER/LESSEE NAME: TIP FLEET SERVICES CANADA LTD, TIP FLEET SERVICES CANADA LTD
ADDRESS: 12516 184 ST NW, 12516 184 ST NW EDMONTON, Alberta T5V1T4, Canada

LICENCED GWV(kg): 0
VEHICLE YEAR: 2008
MAKE: UTILITY
MODEL: VAN

BODY STYLE: Semi Trailer
ODOMETER:
HUB ODOMETER: 172975 KM
BRAKE TYPE: Air
FUEL TYPE: Not Applicable

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) REPLACE MARKER LIGHTS
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) REPLACE LANDING LEGS SAND PADS
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	44	38	6.4	5.6	10.3	10.3	
2	Clamp	30	Automatic	44	38	6.4	5.6	4	4.8	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	85	Lining (Shoe)	14	13	Drum		
2	95	55	Lining (Shoe)	8	18	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: BLANCHARD, ROBERT BRENTON **Signature:** _____

This Inspection Report was submitted to CVSE on 2024-Aug-15 12:08 PM PDT
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement
 CVSE0014