Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number: GN28720
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21722822

Inspection Result: **PASS**

FACILITY:	GROVE TRUCK REPAIRS LTD. / S20376	**INSP. TYPE:**	Complete	**INSP. START:**	2026-Apr-05 01:00 PM PST
INSPECTOR:	KALKAT, SUKHDEEP SINGH / 201124	**INSP. CLASS:**	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	**INSP. COMPLETE:**	2026-Apr-05 03:30 PM PST
WORK ORDER #:		**INSP. REASON:**	Semi-annual		

VEHICLE JUR:	British Columbia	**REGI:**	10604203	**VIN:**	4V4NC9GH77N464451
PLATE #:		**UNIT/FLEET#:**		**OWNER/LESSEE NAME:**	E2E LOGISITICS INC., E2E LOGISITICS INC.
LICENCED GVW(kg):	11388	**BODY STYLE:**	Truck Tractor	**ADDRESS:**	UNIT-303 1621 HAMILTON AVE
VEHICLE YEAR:	2007	**ODOMETER:**	1612441 KM		North Vancouver, British Columbia
MAKE:	VOLVO	**HUB ODOMETER:**			V7P 0B6, Canada
MODEL:		**BRAKE TYPE:**	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	**Repaired (same day)**	REPLACED AXLE#2 RIGHT SIDE AIR BAG.
Section 3 - Brake System	**Repaired (same day)**	REPLACED AXLE#1 LEFT SIDE SLACK ADJUSTER.
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	32	32
2	Clamp	30	Automatic	35	34
3	Clamp	30	Automatic	34	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
8.97			4.47	✔
19.76	20.28	20.65	20.45	
20.28	20.31	20.21	20.6	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	57	60
2	50	50
3	79	54

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	17
Lining (Shoe)	12	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**

Inspector: KALKAT, SUKHDEEP SINGH **Signature:** Sukhdeep Singh

This inspection Report was submitted to CVSE on 2026-Apr-06 11:50 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

4/6/2026 12:24:17 PM PST