

011-2



Commercial Vehicle Inspection Report

Decal Number: GL59988
Decal Expiry Date: 2026-Aug-31
Inspection Number: 21677434

Inspection Result:
PASS

FACILITY: IBK TRUCK & TRAILER REPAIR LTD / S20323	INSP. TYPE: Complete	INSP. START: 2026-Feb-25 02:30 PM PST
INSPECTOR: SIDHU, MAHESHINDER / 301415	INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE: 2026-Feb-25 07:00 PM PST
WORK ORDER #: 3662	INSP. REASON: Semi-annual	

VEHICLE JUR: British Columbia	REGI: 01757946	VIN: 2NPALU0X34M818016
PLATE #: XH4654	UNIT/FLEET#: C6	OWNER/LESSEE NAME: AIR AND OCEANLAND 13 TRANSPORT,
LICENCED GVW(kg): 26000	BODY STYLE: Flat Deck	ADDRESS: 11835-87 AVE
VEHICLE YEAR: 2004	ODOMETER: 928355 KM	Delta, British Columbia
MAKE: PETERBILT	HUB ODOMETER:	V4C 3A2, Canada
MODEL:	BRAKE TYPE: Air	
	FUEL TYPE:	

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	RECENTLY REPLACED 3R BRAKES
Section 3 - Brake System	Passed	RECENTLY REPLACED 3R BROKEN PIGGY BACK
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	31.8	31.8
2	Clamp	30	Automatic	38.1	38.1
3	Clamp	30	Automatic	38.1	38.1

Comment:

Outer L	Inner L	Inner R	Outer R	Steering
21			21	✓
8	8	8	8	
21	21	21	21	

Comment:

Axles	Left	Right
1	45	45
2	50	50
3	45	30

Comment:

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	18	18
Lining (Shoe)	18	21

Comment:

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No Road Test Date: Road Tester:
 Inspector: SIDHU, MAHESHINDER Signature: *Mansh*

This Inspection Report was submitted to CVSE on 2026-Feb-26 02:50 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.