



# Commercial Vehicle Inspection Report

Decal Number: GN16988  
 Decal Expiry Date: 2026-Nov-30  
 Inspection Number: 21789346

Inspection Result:  
**PASS**

**FACILITY:** JUST DIESEL / S7036 **INSP. TYPE:** Complete **INSP. START:** 2026-May-27 04:00 PM PDT  
**INSPECTOR:** FREIMULLER, CURTIS E WALTE / 114909 **INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more **INSP. COMPLETE:** 2026-May-27 06:30 PM PDT  
**WORK ORDER #:** **INSP. REASON:** Semi-annual

**VEHICLE JUR:** British Columbia **REGI:** 04366108 **VIN:** 1NKDL20X9VR946570  
**PLATE #:** XB3478 **UNIT/FLEET#:** **OWNER/LESSEE NAME:** PRATT TRAVIS RYAN,  
**LICENCED GVW(kg):** 43000 **BODY STYLE:** Dump Truck **ADDRESS:** 6395 CAMP CREEK RD  
**VEHICLE YEAR:** 1997 **ODOMETER:** 61871 KM **Prince George, British Columbia**  
**MAKE:** KENWORTH **HUB ODOMETER:** V2N5Z6, Canada  
**MODEL:** **BRAKE TYPE:** Air  
**FUEL TYPE:**

Vehicle Identification (VIN)	Result	Notes
Section 1 - Power Train	Repaired (same day)	TIGHTEN AIR TO AIR, TOP HUB HUB OILS, PINION SEAL SWEATING, STEADY BEARING HAS SLIGHT PLAY
Section 2 - Suspension	Passed with Caution	BUSHINGS WEATHERED
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPAIR RH#2 BRAKE HOSE, REPAIR AIR LEAKS, TIE UP LOOSE HOSES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	REPAIR LIGHTS AS NEEDED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	REPLACE RH CONVEX MIRROR
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	30	30	7			8	✓
2	Clamp	30	Automatic	38	38	18	18	18	16	
3	Clamp	30	Automatic	38	38	17	17	17	16	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	60	Lining (Shoe)	14	14	Drum		
2	45	58	Lining (Shoe)	18	15	Drum		
3	62	70	Lining (Shoe)	15	13	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**  
 Has this Vehicle been road tested? No **Road Test Date:** **Road Tester:**  
**Inspector:** FREIMULLER, CURTIS E WALTE **Signature:**

This Inspection Report was submitted to CVSE on 2026-May-28 11:23 AMPDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.