



# Commercial Vehicle Inspection Report

Decal Number: GD33484  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21008298

Inspection Result:  
**PASS**

<b>FACILITY:</b>	HORIZON DIESEL TRUCK & TRAILER / S11330	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2024-Jul-17 05:45 PM PDT
<b>INSPECTOR:</b>	JATTANA, RAJENDRA / 114347	<b>INSP. CLASS:</b>	Class 3 - Trailer and Semi-Trailer	<b>INSP. COMPLETE:</b>	2024-Jul-18 04:46 PM PDT
<b>WORK ORDER #:</b>	3876	<b>INSP. REASON:</b>	Annual		

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	12679989	<b>VIN:</b>	1UYVS2532FU336122
<b>PLATE #:</b>	16064K	<b>UNIT/FLEET#:</b>	R2049	<b>OWNER/LESSEE NAME:</b>	HIGHWAY KING TRANSPORT LTD.
<b>LICENCED GVW(kg):</b>	0	<b>BODY STYLE:</b>	Semi Trailer	<b>ADDRESS:</b>	2160 PEARDONVILLE RD Abbotsford, British Columbia V2T6J8, Canada
<b>VEHICLE YEAR:</b>	2015	<b>ODOMETER:</b>			
<b>MAKE:</b>	UTILITY	<b>HUB ODOMETER:</b>			
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) REPLACE BRAKE POT ON # 1L.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	10	9	7	9	
2	Disc	N/A	Not Applicable	0	0	10	10	10	10	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right		Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	0	0		Pad	14	15	Rotor	38.92	43.32
2	0	0		Pad	18	14	Rotor	43.64	41.80
Comment:				Comment:			Comment:		

**Inspection Comments:**  
 Has this Vehicle been road tested?  No **Road Test Date:** \_\_\_\_\_ **Road Tester:** \_\_\_\_\_  
**Inspector:** JATTANA, RAJENDRA **Signature:** *R. Jattana*

This inspection Report was submitted to CVSE on 2024-Jul-18 04:47 PM PDT  
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.