



Commercial Vehicle Inspection Report

Decal Number: GL06511
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21496403

P062 Inspection Result:
PASS

ACILITY:	METRO TRUCK AND TRAILER REPAIR / S11850	INSP. TYPE:	Complete	INSP. START:	2025-Sep-13 06:15 PM PDT
INSPECTOR:	SEKHON, NARINDER / 300468	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Sep-13 08:20 PM PDT
WORK ORDER #:	010534	INSP. REASON:	Semi-annual		
EHICLE JUR:	British Columbia	REGI:	13219552	VIN:	1XPBD49X7LD709735
LATE #:	91971P	UNIT/FLEET#:	792	OWNER/LESSEE NAME:	HAP, HAP TRUCKING LTD.
ICENCED GVW(kg):	47000	BODY STYLE:	Truck Tractor	ADDRESS:	7954 WEBSTER ROAD, 7954 WEBSTER ROAD
EHICLE YEAR:	2020	ODOMETER:	1422856 KM		Delta, British Columbia
AKE:	PETERBILT	HUB ODOMETER:			V4G1G6, Canada
ODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)

Passed

Section 1 - Power Train

Passed

Section 2 - Suspension

Repaired (same day) REPLACED 2RHS SPRING BUSHING

Section 3 - Brake System

Passed

Section 3A- Air Brakes

Passed

Section 3H - Hydraulic Brakes

Not Applicable

Section 4 - Steering

Passed

Section 5 - Instruments and Auxiliary Equipment

Passed

Section 6 - Lamps

Passed

Section 7 - Electrical System

Passed

Section 8 - Frame and Body

Passed

Section 9A- Tires

Repaired (same day) REPLACED 3RHS TIRES

Section 9B - Wheels

Passed

Section 10 - Coupling Devices

Passed

Section 11 - Other Vehicle Components

Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

_AXLES	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	36	36	6.4			8.7	✓
2	Clamp	30L	Automatic	36	36	21.4	21.4	21.4	21.4	
3	Clamp	30L	Automatic	34	36	18.3	18.3	6.4	7.9	

Comment:

Comment:

Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

_AXLES	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	75	Lining (Shoe)	16	13	Drum	419.70	420.10
2	75	25	Lining (Shoe)	14	21	Drum	420.50	419.10
3	83	75	Lining (Shoe)	13	14	Drum	420.90	420.40

Comment:

Comment:

Comment:

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: SEKHON, NARINDER

Signature: 

This Inspection Report was submitted to CVSE on 2025-Sep-13 11:14 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

DO NOT KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized Inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

NSCVP

13/2025 11:15:25 PM PDT