

Commercial Vehicle Inspection Report

Decal Number: **GH98603**
 Decal Expiry Date: **2026-Mar-31**
 Inspection Number: **21268052**

Inspection Result: **PASS**

PO9-5

FACILITY:	BRIGHT QUALITY ENTERPRISES LTD / S15780	INSP. TYPE:	Complete	INSP. START:	2025-Mar-12 09:30 AM PDT
INSPECTOR:	KAILA, JOBAN SINGH / 202325	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Mar-12 10:45 AM PDT
WORK ORDER #:		INSP. REASON:	Annual		

VEHICLE JUR:	British Columbia	REGI:	12048744	VIN:	503256
PLATE #:		UNIT/FLEET#:	5327	OWNER/LESSEE NAME:	TWENTY FIVE EIGHT LOGISTICS, TWENTY FIVE EIGHT LOGISTICS
LICENCED GVW(kg):	999999	BODY STYLE:	Van Trailer	ADDRESS:	PO BOX 98036 RPO SINSHINE VILLA
VEHICLE YEAR:	2015	ODOMETER:			Delta, British Columbia
MAKE:	VANGUARD	HUB ODOMETER:			V4E3M9, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	33	32
2	Clamp	30	Automatic	33	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	10	10	10	
9	9	8	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	65
2	60	65

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	14
Lining (Shoe)	16	16

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: KAILA, JOBAN SINGH

Signature:

This Inspection Report was submitted to CVSE on 2025-Mar-12 02:01 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement

CVSE0014

3/12/2025 2:01:47 PM PDT

1. The first part of the report is a general introduction to the subject of the study.

2. The second part of the report is a detailed description of the methods used in the study.

3. The third part of the report is a discussion of the results of the study.

4. The fourth part of the report is a conclusion and a list of references.

5. The fifth part of the report is a list of appendices.

6. The sixth part of the report is a list of figures and tables.

7. The seventh part of the report is a list of footnotes.

8. The eighth part of the report is a list of references.

9. The ninth part of the report is a list of appendices.

10. The tenth part of the report is a list of figures and tables.

11. The eleventh part of the report is a list of footnotes.

12. The twelfth part of the report is a list of references.

13. The thirteenth part of the report is a list of appendices.

14. The fourteenth part of the report is a list of figures and tables.

15. The fifteenth part of the report is a list of footnotes.