



# Commercial Vehicle Inspection Report

Decal Number: GF45287  
Decal Expiry Date: 2025-Oct-31  
Inspection Number: 21330400

Inspection Result:

**PASS**

<b>FACILITY:</b>	SECHLT TRUCK AND EQUIPMENT / S6977	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Apr-29 09:15 AM PDT
<b>INSPECTOR:</b>	POPP, WESLEY SHAWN / 114349	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2025-Apr-29 02:16 PM PDT
<b>WORK ORDER #:</b>	63163	<b>INSP. REASON:</b>	Semi-annual		
<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	11393221	<b>VIN:</b>	3AKJGLD59SGZ8415
<b>PLATE #:</b>	22999P	<b>UNIT/FLEET#:</b>		<b>OWNER/LESSEE NAME:</b>	HORVATH PATRICK, JOSEPH
<b>LICENCED GVW(kg):</b>	63500	<b>BODY STYLE:</b>	Truck Tractor	<b>ADDRESS:</b>	6065 MASON RD
<b>VEHICLE YEAR:</b>	2016	<b>ODOMETER:</b>	823574 KM		Sechelt, British Columbia
<b>MAKE:</b>	FREIGHTLIN	<b>HUB ODOMETER:</b>			VON3A8, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed with Caution	#3R PADS NEARING LIMIT
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Repaired (same day)	ROTATED FRONT TIRES ON RIMS, REPAIRED #3L INNER FLAT
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Tire Tread Depth (mm)				Steering
						Outer L	Inner L	Inner R	Outer R	
1	Disc	N/A	Not Applicable	0	0	11			10	✓
2	Disc	N/A	Not Applicable	0	0	5	8	5	6	
3	Disc	N/A	Not Applicable	0	0	7	6	5	5	

Comment: DISC

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	0	0
2	0	0
3	0	0

Comment: N/A

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Pad	15	16
Pad	17	17
Pad	13	11


Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Rotor	0.00	0.00
Rotor	0.00	0.00
Rotor	0.00	0.00

Comment: DNPW

## Inspection Comments:

Has this Vehicle been road tested? No Road Test Date:  Road Tester:

Inspector: POPP, WESLEY SHAWN Signature:

This Inspection Report was submitted to CVSE on 2025-Apr-29 02:22 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

295 +

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

4/29/2025 2:22:32 PM PDT