

ROY-1



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ18390
Decal Expiry Date: 2026-Jun-30
Inspection Number: 21376066

Inspection Result:
PASS

FACILITY: 5 POINT HEAVY EQUIPMENT / S6720
INSPECTOR: BLACKMORE, CODY MICHAEL / 300295
WORK ORDER #: 9053

INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual

INSP. START: 2025-Jun-03 08:59 AM PDT
INSP. COMPLETE: 2025-Jun-03 09:59 AM PDT

VEHICLE JUR: British Columbia
PLATE #: 52298K
REGI: 00517446
UNIT/FLEET#: 532V110
VIN: 1GRAA06281B154817
OWNER/LESSEE NAME: CENTRAL ISLAND DIST. CENTRAL ISLAND DIST. CENTRAL
ADDRESS: 2050 BALSAM RD. Nanaimo, British Columbia V9X1T5, Canada

LICENCED GVW(kg): 999999
VEHICLE YEAR: 2001
MAKE: GREAT DANE
MODEL:

BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Section	Result	Comments
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	customer replaced L1 R1,R2 shock
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed with Caution	Rear bumper end cap rotten but not structural
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axes	Type	Size	Shock Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	33	32	10	10	12	12	
2	Clamp	30	Automatic	32	31	8	8	9	7	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)				
Axes	Left	Right	Lining/Pad		Left	Right	Rotor/Drum		Left	Right
1	38	40	Lining (Shoe)		20	20	Drum			
2	55	62	Lining (Shoe)		17	16	Drum			

Comment: Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No
 Road Test Date: _____ Road Tester: _____
 Inspector: BLACKMORE, CODY MICHAEL Signature:

This inspection Report was submitted to CVSE on 2025-Jun-03 09:59 AM PDT
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.