



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD49683
Decal Expiry Date: 2025-Mar-31
Inspection Number: 21072586

Inspection Result:
PASS

R05-5

FACILITY:	TRIPLE S TRUCK TIRES & TRAILER REPAIR LTD. / S14100	INSP. TYPE:	Complete	INSP. START:	2024-Sep-14 08:03 AM PDT
INSPECTOR:	Dhaliwal, Rajinder Singh / 203186	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2024-Sep-15 12:12 PM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11211969	VIN:	4V4NC9EH9FN910973
PLATE #:	RH0331	UNIT/FLEET#:	G457	OWNER/LESSEE NAME:	GULZAR TRANSPORT INC., GULZAR TRANSPORT INC.
LICENCED GVW(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	8760 RIVER RD
VEHICLE YEAR:	2015	ODOMETER:	1298722 KM		Delta, British Columbia
MAKE:	VOLVO	HUB ODOMETER:			V4G1B5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) XL2 AND XL3 L/S BREAK REPLACED
Section 3A - Air Brakes	Repaired (same day) AIR FIXED AT AIR COMPRESSURE AND FIREWALL
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Repaired (same day) WIPER BLADE AND ARMS REPLACED
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) TRANSXY COOLER LINES SECURED
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) XL1 BOTH SIDE OIL FILLED
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	34	35	11			12	✓
2	Clamp	30	Automatic	36	35	12	12	11	11	
3	Clamp	30	Automatic	35	36	6	6	6	6	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	83	49
2	39	78
3	37	59

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	16
Lining (Shoe)	21	13
Lining (Shoe)	21	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment:

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Dhaliwal, Rajinder Singh

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Sep-15 12:13 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSED014

9/15/2024 12:13:15 PM PDT