



Commercial Vehicle Inspection Report

Decal Number: GD97063
Decal Expiry Date: 2025-Apr-30
Inspection Number: 21113163

Inspection Result: **PASS** Ros-6

FACILITY: TRIPLE S TRUCK TIRES & TRAILER REPAIR LTD. / S14100
INSPECTOR: Dhaliwal, Rajinder Singh / 203186
WORK ORDER #:

INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual

INSP. START: 2024-Oct-19 08:00 AM PDT
INSP. COMPLETE: 2024-Oct-19 01:00 PM PDT

VEHICLE JUR: British Columbia
PLATE #: RF6432

REGI: 10447188
UNIT/FLEET#: J493

VIN: 4V4NC9EJ5DN568762
OWNER/LESSEE NAME: JET SPEED TRANSPORT LTD., JET SPEED TRANSPORT LTD.

LICENCED GVW(kg): 43000
VEHICLE YEAR: 2013
MAKE: VOLVO
MODEL:

BODY STYLE: Truck Tractor
ODOMETER: 1646724 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel

ADDRESS: 7-8760 RIV
Delta, British Columbia
V4G1B5, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Repaired (same day) FIRST DEF INPUT DEF SEAL AND OUTPUT DEF SEAL AND YOKE REPLACED
Section 2 - Suspension	Repaired (same day) XL2 AND XL3 BOTH SIDE SHOCK AND U-BOLT REPLACED AND XL3 R/S AIR BAG REPLACED
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) XL2 R/S BREAK NEW AND AIR FIXED AT TRANSMISSION
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) R/S FOG LAMP FIXED
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) BOTH SIDE STEP FAIRING FIXED
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) FIFTH WHEEL ADJUSTED
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	34	34
2	Clamp	30	Automatic	36	35
3	Clamp	30	Automatic	36	35

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13			13	✓
9	9	6	9	
7	7	22	22	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	85	83
2	60	26
3	62	61

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	12	12
Lining (Shoe)	15	21
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	0.00
Drum	0.00	0.00
Drum	0.00	0.00

Comment: XL2 R/S DRUM NEW

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: Dhaliwal, Rajinder Singh

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Oct-19 04:39 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSED014

10/19/2024 4:39:47 PM PDT