



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ38516
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21437959

Inspection Result:

PASS

R19-1

FACILITY: P & R TRUCK CENTRE LTD. / S20318
INSPECTOR: Infanti, Kyle Christopher / 203397
WORK ORDER #: R-2540
INSPECTION TYPE: Complete
INSPECTION CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSPECTION REASON: Semi-annual
INSPECTION START: 2025-Jul-14 08:08 AM PDT
INSPECTION COMPLETE: 2025-Jul-25 08:08 AM PDT

VEHICLE JUR: Saskatchewan
PLATE #:
LICENCED GWV(kg): 24300
VEHICLE YEAR: 1998
MAKE: FORD
MODEL:
REGI:
UNIT/FLEET#:
BODY STYLE: Truck
ODOMETER: 483733 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE: Diesel
VIN: 1FDYS96B1WVA15494
OWNER/LESSEE NAME: DEAN FERGUSON,
ADDRESS: 1630 SHERWOOD DR
Nanaimo, British Columbia
V9T 1H3, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) RUBBER BLOCKS ON SUSPENSION WORN
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) #2L WHEEL SEAL #3L AND R WHEEL SEAL
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) DRAG LINK WORN
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	38.1	38.1	12			12	✓
2	Clamp	30	Automatic	47.6	50.8	15	15	15	15	
3	Clamp	30	Automatic	47.6	47.6	14	15	14	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	50
2	45	45
3	45	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	17
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: Infanti, Kyle Christopher

Signature: 

This Inspection Report was submitted to CVSE on 2025-Jul-25 08:09 AMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/25/2025 8:09:05 AMPDT