

Rb5-2



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GD14990
Decal Expiry Date: 2025-Jul-31
Inspection Number: 21010053

Inspection Result:
PASS

FACILITY:

INSPECTOR:

WORK ORDER #:

SRT DIESEL TRUCK & TRAILER
REPAIR LTD. / S11361
DHALIWAL, SATWANT SINGH /
114414
11060

INSP. TYPE:

INSP. CLASS:

INSP. REASON:

Complete
Class 3 - Trailer and Semi-Trailer
Annual

INSP. START:

INSP. COMPLETE:

2024-Jul-20 09:00 AM PDT

2024-Jul-20 11:00 AM PDT

VEHICLE JUR:

PLATE #:

British Columbia
04768J

REGI:

UNIT/FLEET#:

12135545
D500

VIN:

OWNER/LESSEE NAME:

1UYVS2531J7161711
PANTHER EXPRESS LTD. (LESSEE),
CWB NATIONAL LEASING INC.
(LESSOR)
3563 THURSTON PL
Abbotsford, British Columbia
V2T 6Y2, Canada

LICENCED GVW(kg): 0

VEHICLE YEAR:

MAKE:

MODEL:

2018
UTILITY

BODY STYLE:

ODOMETER:

HUB ODOMETER:

BRAKE TYPE:

FUEL TYPE:

Van Trailer

Air

Vehicle Identification (VIN)

Section 1 - Power Train

Section 2 - Suspension

Section 3 - Brake System

Section 3A - Air Brakes

Section 3H - Hydraulic Brakes

Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Section 6 - Lamps

Section 7 - Electrical System

Section 8 - Frame and Body

Section 9A - Tires

Section 9B - Wheels

Section 10 - Coupling Devices

Section 11 - Other Vehicle Components

Passed

Not Applicable

Repaired (same day)

Passed

Repaired (same day)

Not Applicable

Not Applicable

Not Applicable

Passed

Passed

Passed

Passed

Passed

Passed

Not Applicable

REPLACED THE SUSPENSION CONTROL VALVE

REPLACED THE BRAKE CHAMBERS ON 1XL RH SIDE & 2XL RH SIDE

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	32	32

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
5.6	4	3.2	4	
4.8	4.8	6.4	5.6	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	57	50
2	70	63

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	13	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector:

DHALIWAL, SATWANT SINGH

Signature:

Road Tester:

This inspection Report was submitted to CVSE on 2024-Jul-20 01:17 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/20/2024 1:17:14 PM PDT

