



Commercial Vehicle Inspection Report

Decal Number: GL04410
 Decal Expiry Date: 2026-Sep-30
 Inspection Number: 21511413

R65-1
 Inspection Result:
PASS

FACILITY: MOGA TRUCK REPAIR LTD / S20362
INSPECTOR: BRAR, HARJIT SINGH / 110837
WORK ORDER #: 18388
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Sep-24 07:00 PM PDT
INSP. COMPLETE: 2025-Sep-25 07:30 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 43314K
LICENCED GVW(kg): 0
VEHICLE YEAR: 2023
MAKE: VANGUARD
MODEL:
REGI: 14121611
UNIT/FLEET#: v2032
BODY STYLE: Van, Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 5V8VC532XPT308483
OWNER/LESSEE NAME: RELIANCE LOGISTICS , BC INC
ADDRESS: 9575 180 ST
 Surrey, British Columbia
 V4N3V6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AXCEL 1 LEFT MAXY REPLACE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxillary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	32
2	Clamp	30	Automatic	30	30

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	10	10	8	8	
	9	9	9	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	45	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.00	419.00
Drum	419.00	419.00

Comment:

Inspection Comments:
 Has this Vehicle been road tested? No **Road Test Date:** _____ **Road Tester:** _____
Inspector: BRAR, HARJIT SINGH **Signature:** 

This Inspection Report was submitted to CVSE on 2025-Sep-26 12:59 PM PDT
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.