



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GL04410
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21511413

Inspection Result:

PASS

R65-5

FACILITY: MOGA TRUCK REPAIR LTD / S20362
INSPECTOR: BRAR, HARJIT SINGH / 110837
WORK ORDER #: 18388
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2025-Sep-24 07:00 PM PDT
INSP. COMPLETE: 2025-Sep-25 07:30 PM PDT

VEHICLE JUR: British Columbia
PLATE #: 43314K
LICENCED GWV(kg): 0
VEHICLE YEAR: 2023
MAKE: VANGUARD
MODEL:
REGI: 14121611
UNIT/FLEET#: v2032
BODY STYLE: Van, Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
VIN: 5V8VC532XPT308483
OWNER/LESSEE NAME: RELIANCE LOGISTICS, BC INC
ADDRESS: 9575 180 ST
Surrey, British Columbia
V4N3V6, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) AXCEL 1 LEFT MAXY REPLACE
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	32	22
2	Clamp	30	Automatic	30	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
10	10	8	8	
9	0	9	9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	45	45

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	21	21
Lining (Shoe)	21	21

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	419.00	419.00
Drum	419.00	419.00

Comment:

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: BRAR, HARJIT SINGH

Signature:

[Handwritten Signature]

This Inspection Report was submitted to CVSE on 2025-Sep-26 12:59 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/26/2025 12:59:40 PM PDT