



# Commercial Vehicle Inspection Report

Decal Number: GK86247  
Decal Expiry Date: 2026-Sep-30  
Inspection Number: 21493493

Inspection Result: <sup>K64-1</sup>  
**PASS** ✓

**FACILITY:** RYDER TRUCK RENTAL - DELTA / S4595  
**INSPECTOR:** Turpin, Bryan Keith / 109876  
**WORK ORDER #:**

**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Annual

**INSP. START:** 2025-Sep-11 12:02 PM PDT  
**INSP. COMPLETE:** 2025-Sep-11 01:02 PM PDT


**VEHICLE JUR:** Unknown  
**PLATE #:**  
**LICENCED GVW(kg):** 8850  
**VEHICLE YEAR:** 2019  
**MAKE:** Hino  
**MODEL:** xdc720

**REGI:**  
**UNIT/FLEET#:** 143624  
**BODY STYLE:** Truck  
**ODOMETER:** 160426 KM  
**HUB ODOMETER:**  
**BRAKE TYPE:** Hydraulic  
**FUEL TYPE:** Diesel

**VIN:** 2AYRDM2H9K1001248  
**OWNER/LESSEE NAME:** Truck Rental, Ryder  
**ADDRESS:** 1699 Cliveden Ave  
Annacis, British Columbia  
v3j5w7, Canada

- Vehicle Identification (VIN) Passed
- Section 1 - Power Train Passed
- Section 2 - Suspension Passed
- Section 3 - Brake System Passed
- Section 3H - Hydraulic Brakes Passed
- Section 4 - Steering Passed
- Section 5 - Instruments and Auxiliary Equipment Passed
- Section 6 - Lamps Passed
- Section 7 - Electrical System Passed
- Section 8 - Frame and Body Passed
- Section 9A - Tires Passed
- Section 9B - Wheels Passed
- Section 10 - Coupling Devices Not Applicable
- Section 11 - Other Vehicle Components Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	14			14	✓	Pad	14	14	Rotor	35.00	35.00
2	13	13	13	13		Pad	16	16	Rotor	35.00	35.00

**Inspection Comments:**  
Has this Vehicle been road tested? No  
**Inspector:** Turpin, Bryan Keith  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2025-Sep-11 01:02 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.