

76

# Commercial Vehicle Inspection Report

Decal Number: GK86376  
Decal Expiry Date: 2026-May-31  
Inspection Number: 21565778

Inspection Result:  
**PASS**

<b>FACILITY:</b> RYDER TRUCK RENTAL - DELTA / S4595	<b>INSP. TYPE:</b> Complete	<b>INSP. START:</b> 2025-Nov-13 08:22 AM PST
<b>INSPECTOR:</b> Blades, Glenn Russell / 112756	<b>INSP. CLASS:</b> Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b> 2025-Nov-13 09:22 AM PST
<b>WORK ORDER #:</b>	<b>INSP. REASON:</b> Semi-annual	

<b>VEHICLE JUR:</b> British Columbia	<b>REGI:</b> 12026591	<b>VIN:</b> 3ALHCYCY5HDHJ1973
<b>PLATE #:</b>	<b>UNIT/FLEET#:</b> 671787	<b>OWNER/LESSEE NAME:</b> ryder, truck rental
<b>LICENCED GVW(kg):</b> 24494	<b>BODY STYLE:</b> Van	<b>ADDRESS:</b> 1699 cliveden ave
<b>VEHICLE YEAR:</b> 2017	<b>ODOMETER:</b> 186322 KM	Delta, British Columbia
<b>MAKE:</b> FREIGHTLIN	<b>HUB ODOMETER:</b>	v3m6v5, Canada
<b>MODEL:</b>	<b>BRAKE TYPE:</b> Air	
	<b>FUEL TYPE:</b>	

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	20L	Automatic	38.1	38.1	5.6			7.9	✓
2	Clamp	30L	Automatic	50.8	50.8	7.9	7.9	7.9	7.9	
3	Clamp	30L	Automatic	50.8	50.8	7.9	7.9	7.9	7.9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	80	Lining (Shoe)	15.9	15.9	Drum		
2	75	75	Lining (Shoe)	14.3	14.3	Drum		
3	75	75	Lining (Shoe)	14.3	14.3	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

**Inspection Comments:**

Has this Vehicle been road tested? No      Road Test Date: \_\_\_\_\_      Road Tester: \_\_\_\_\_  
 Inspector: Blades, Glenn Russell      Signature: 

This Inspection Report was submitted to CVSE on 2025-Nov-13 09:25 AMPST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVF at the Commercial Vehicle Safety Enforcement.