



BRITISH  
COLUMBIA

# Commercial Vehicle Inspection Report

Decal Number: GH13509  
Decal Expiry Date: 2025-Jul-31  
Inspection Number: 21214938

Inspection Result:

**PASS**

R69-4

|                      |                                    |                      |                                                   |                        |                          |
|----------------------|------------------------------------|----------------------|---------------------------------------------------|------------------------|--------------------------|
| <b>FACILITY:</b>     | RYDER TRUCK RENTAL - DELTA / S4595 | <b>INSP. TYPE:</b>   | Complete                                          | <b>INSP. START:</b>    | 2025-Jan-23 08:56 AM PST |
| <b>INSPECTOR:</b>    | Blades, Glenn Russell / 112756     | <b>INSP. CLASS:</b>  | Class 2 - Heavy Vehicle with LGVW 5501 kg or more | <b>INSP. COMPLETE:</b> | 2025-Jan-23 09:56 AM PST |
| <b>WORK ORDER #:</b> |                                    | <b>INSP. REASON:</b> | Semi-annual                                       |                        |                          |

  

|                          |                  |                      |               |                           |                         |
|--------------------------|------------------|----------------------|---------------|---------------------------|-------------------------|
| <b>VEHICLE JUR:</b>      | British Columbia | <b>REGI:</b>         | 12907157      | <b>VIN:</b>               | 1FUJHFG9LLC9268         |
| <b>PLATE #:</b>          |                  | <b>UNIT/FLEET#:</b>  | 876539        | <b>OWNER/LESSEE NAME:</b> | ryder, truck rental     |
| <b>LICENCED GVW(kg):</b> | 41000            | <b>BODY STYLE:</b>   | Truck Tractor | <b>ADDRESS:</b>           | 1699 cliveden ave       |
| <b>VEHICLE YEAR:</b>     | 2020             | <b>ODOMETER:</b>     | 1031907 KM    |                           | Delta, British Columbia |
| <b>MAKE:</b>             | FREIGHTLIN       | <b>HUB ODOMETER:</b> |               |                           | v3m6v5, Canada          |
| <b>MODEL:</b>            |                  | <b>BRAKE TYPE:</b>   | Air           |                           |                         |
|                          |                  | <b>FUEL TYPE:</b>    | Diesel        |                           |                         |

|                                                 |                |
|-------------------------------------------------|----------------|
| Vehicle Identification (VIN)                    | Passed         |
| Section 1 - Power Train                         | Passed         |
| Section 2 - Suspension                          | Passed         |
| Section 3 - Brake System                        | Passed         |
| Section 3A - Air Brakes                         | Passed         |
| Section 3H - Hydraulic Brakes                   | Not Applicable |
| Section 4 - Steering                            | Passed         |
| Section 5 - Instruments and Auxiliary Equipment | Passed         |
| Section 6 - Lamps                               | Passed         |
| Section 7 - Electrical System                   | Passed         |
| Section 8 - Frame and Body                      | Passed         |
| Section 9A - Tires                              | Passed         |
| Section 9B - Wheels                             | Passed         |
| Section 10 - Coupling Devices                   | Passed         |
| Section 11 - Other Vehicle Components           | Not Applicable |

| Air Brake Chamber Type, Size and Push Rod Stroke (mm) |       |      |            | Tire Tread Depth (mm) |       |         |         |         |         |          |
|-------------------------------------------------------|-------|------|------------|-----------------------|-------|---------|---------|---------|---------|----------|
| Axles                                                 | Type  | Size | Slack Adj. | Left                  | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1                                                     | Clamp | 24L  | Automatic  | 38.1                  | 38.1  | 9.5     |         |         | 10.3    | ✓        |
| 2                                                     | Clamp | 30L  | Automatic  | 44.5                  | 44.5  | 13.5    | 15.9    | 13.5    | 12.7    |          |
| 3                                                     | Clamp | 30L  | Automatic  | 44.5                  | 44.5  | 10.3    | 12.7    | 12.7    | 12.7    |          |
| Comment:                                              |       |      |            | Comment:              |       |         |         |         |         |          |

| Air Brake Camshaft Rotation (degrees) |      |       | Brake Lining/Pad (mm) |      |       | Rotor Thickness or Drum Inside Diameter (mm)                                                   |      |       |
|---------------------------------------|------|-------|-----------------------|------|-------|------------------------------------------------------------------------------------------------|------|-------|
| Axles                                 | Left | Right | Lining/Pad            | Left | Right | Rotor/Drum                                                                                     | Left | Right |
| 1                                     | 45   | 45    | Lining (Shoe)         | 17.5 | 17.5  | Drum                                                                                           |      |       |
| 2                                     | 60   | 60    | Lining (Shoe)         | 15.9 | 15.9  | Drum                                                                                           |      |       |
| 3                                     | 90   | 90    | Lining (Shoe)         | 12.7 | 12.7  | Drum                                                                                           |      |       |
| Comment:                              |      |       | Comment:              |      |       | Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured. |      |       |

**Inspection Comments:**  
 Has this Vehicle been road tested? No Road Test Date:   
 Inspector: Blades, Glenn Russell Signature:

This Inspection Report was submitted to CVSE on 2025-Jan-23 09:57 AM PST  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSED014

1/23/2025 9:57:23 AM PST

