



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GJ85864
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21396547

Inspection Result:

PASS

FACILITY:	RYDER TRUCK RENTAL - DELTA / S4595	INSP. TYPE:	Complete	INSP. START:	2025-Jun-19 11:56 AM PDT
INSPECTOR:	Blades, Glenn Russell / 112756	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jun-19 12:56 PM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	12907170	VIN:	1FUJHHFG3LLLC9265
PLATE #:		UNIT/FLEET#:	876536	OWNER/LESSEE NAME:	ryder, truck rental
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	1699 cliveden ave
VEHICLE YEAR:	2020	ODOMETER:	703206 KM		Delta, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			v3m6v5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	38.1	38.1	7.9			7.9	✓
2	Clamp	30L	Automatic	44.5	44.5	8.7	7.1	7.9	7.1	
3	Clamp	30L	Automatic	44.5	44.5	19.1	18.3	3.2	3.2	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	45	45	Lining (Shoe)	15.9	15.9	Drum		
2	60	60	Lining (Shoe)	15.9	15.9	Drum		
3	60	60	Lining (Shoe)	15.9	15.9	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: Blades, Glenn Russell

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-19 12:57 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/19/2025 12:57:26 PM PDT