



Commercial Vehicle Inspection Report

Decal Number: GK86363
Decal Expiry Date: 2026-Nov-30
Inspection Number: 21558681

Inspection Result: **PASS** *K69-8*

FACILITY: RYDER TRUCK RENTAL - DELTA/S4595
INSPECTOR: Blades, Glenn Russell / 112756
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Annual
INSP. START: 2025-Nov-06 08:29 AM PST
INSP. COMPLETE: 2025-Nov-06 09:29 AM PST

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 14969
VEHICLE YEAR: 2018
MAKE: INTERNATNA
MODEL:
REGI: 12615050
UNIT/FLEET#: 221227
BODY STYLE: Van
ODOMETER: 395557 KM
HUB ODOMETER:
BRAKE TYPE: Hydraulic
FUEL TYPE:
VIN: 1HTMMMP3JH335814
OWNER/LESSEE NAME: ryder, truck rental
ADDRESS: 1699 cliveden ave
Delta, British Columbia
v3m6v5, Canada

| | |
|---|----------------|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Passed |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Passed |
| Section 3H - Hydraulic Brakes | Passed |
| Section 4 - Steering | Passed |
| Section 5 - Instruments and Auxiliary Equipment | Passed |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Not Applicable |
| Section 11 - Other Vehicle Components | Not Applicable |

| Tire Tread Depth (mm) | | | | | | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | |
|-----------------------|---------|---------|---------|---------|----------|-----------------------|------|-------|--|-------|-------|
| Axles | Outer L | Inner L | Inner R | Outer R | Steering | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
| 1 | 15.1 | | | 15.1 | ✓ | Pad | 12.7 | 12.7 | Rotor | 37.04 | 37.06 |
| 2 | 13.5 | 13.5 | 13.5 | 12.7 | | Pad | 9.5 | 9.5 | Rotor | 37.01 | 37.05 |

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: Blades, Glenn Russell
Road Test Date:
Signature: *[Signature]* **Road Tester:**

This Inspection Report was submitted to CVSE on 2025-Nov-06 09:30 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.