


506



Commercial Vehicle Inspection Report

Decal Number: GK51516
Decal Expiry Date: 2028-Aug-31
Inspection Number: 21448410

Inspection Result:
PASS

ACTIVITY: METRO TRUCK AND TRAILER REPAIR / S11850
INSPECTOR: SEKHON, NARINDER / 300468
WORK ORDER #: 010230

INSR. TYPE: Complete
INSR. CLASS: Class 3 - Trailer and Semi-Trailer
INSR. REASON: Annual

INSR. START: 2025-Aug-01 01:15 PM PDT
INSR. COMPLETE: 2025-Aug-01 03:25 PM PDT

VEHICLE JUR: British Columbia
LATE #: 14809L

REGI: 12725041
UNIT/FLEET#: 53328

VIN: 5V8VA53B7KM800013
OWNER/LESSEE NAME: ROADWAY, ROADWAY TRANSPORT LTD.
ADDRESS: 7954 WEBSTER ROAD, 7954 WEBSTER ROAD
 Delta, British Columbia
 V4G1G6, Canada

LICENSED GVW(kg): 999999
BODY STYLE: Van Trailer

VEHICLE YEAR: 2019
MAKE: VANGUARD
MODEL:

ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Result
Section 1 - Power Train	Passed
Section 2 - Suspension	Not Applicable
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACE AX 2 RHS SLACK ADJUSTER AND S-CAM BUSHING
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Not Applicable
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) REPLACE BOTH GLAND HANDS
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	36	36	4.9	6	9.9	9.3	
2	Clamp	30	Automatic	34	36	10.2	9.9	7.7	8.5	
3	Clamp	30	Automatic	36	34	11	11	5.5	6.9	

Comment: _____

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	80	60	Lining (Shoe)	16	17	Drum	421.10	420.95
2	80	50	Lining (Shoe)	16	18	Drum	421.10	420.20
3	55	45	Lining (Shoe)	16	18	Drum	420.30	420.10

Comment: _____

Inspection Comments:
 Has this vehicle been road tested? No
 Inspector: SEKHON, NARINDER
 Road Test Date: _____
 Signature: 
 Road Tester: _____

This inspection report was submitted to CVSE on 2025-Aug-01 11:15 PM PDT
 The inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCV/P at the Commercial Vehicle Safety Enforcement
 VSE0014
 1/2025 11:15:23 PM PDT