



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: **GK64328**
Decal Expiry Date: **2026-Feb-28**
Inspection Number: **21472646**

Inspection Result:
PASS

FACILITY:	SANDHER TRUCK & TRAILER REPAIR LTD. / 815370	INSR. TYPE:	Complete	INSR. START:	2025-Aug-25 10:00 AM PDT
INSPECTOR:	SANDHAR, DAVINDERJIT / 202087	INSR. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSR. COMPLETE:	2025-Aug-25 12:30 PM PDT
WORK ORDER #:		INSR. REASON:	Self-annual		

VEHICLE JUR:	British Columbia	REG#:	10084806	VIN:	1FUGP0R28DAYS899
PLATE #:	85357P	UNIT/FLEET#:	2140	OWNER/LESSEE NAME:	BRONCO, TRANSPORTATION SYSTEM
LICENCED GVW(kg):	48500	BODY STYLE:	Truck Tractor	ADDRESS:	201 9078 RIVER RD
VEHICLE YEAR:	2011	ODOMETER:	1637155 KM		Delta, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			V4G1B5, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACE 2ND AXLE RLS LEAF SPRING BUSHING
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Stroke Adj.	Left	Right
1	Clamp	24L	Automatic	32	32
2	Clamp	30L	Automatic	38	38
3	Clamp	30L	Automatic	38	38

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	6.7			6.8	✓
2	6.7	6.7	14.3	14.3	
3	14.3	14.3	14.3	14.3	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	50	50
3	50	50

Comment:

Brake Lining/Pad (mm)

	Left	Right
Lining/Pad	17	17
Lining (Shoe)	18	17
Lining (Shoe)	18	18

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? **No** Road Test Date: Road Tester:
Inspector: **SANDHAR, DAVINDERJIT** Signature:

This Inspection Report was submitted to CVSE on 2025-Aug-25 03:34 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and/or generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement.

CVSE0014

6/25/2025 3:36:57 PM PDT