



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GB17937
Decal Expiry Date: 2025-Jan-31
Inspection Number: 20777613

Inspection Result: **PASS** 513-5

FACILITY:	OCEAN TRAILER / S8173	INSP. TYPE:	Complete	INSP. START:	2024-Jan-03 02:00 AM PST
INSPECTOR:	MORGAN, DEAN / 111668	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2024-Jan-03 03:00 AM PST
WORK ORDER #:	289124	INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	13993198	VIN:	2M592161XX1179595
PLATE #:	36807K	UNIT/FLEET#:	V1007	OWNER/LESSEE NAME:	MERIDAN ONE CAP CREDIT CORP, TRANSHUB LOGISTICS LTD
LICENCED GVW(kg): 0		BODY STYLE:	Van Trailer	ADDRESS:	PO BOX98057 SCOTTDALLE PO Delta, British Columbia V4E3M9, Canada
VEHICLE YEAR:	2019	ODOMETER:			
MAKE:	MANAC	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	32	32	8	9	9	9	
2	Clamp	30	Automatic	32	32	8	10	15	15	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	41	40	Lining (Shoe)	18	18	Drum	16.51	16.51	
2	65	58	Lining (Shoe)	14	14	Drum	16.53	16.53	
Comment:			Comment:			Comment:			

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: MORGAN, DEAN Signature: _____

This Inspection Report was submitted to CVSE on 2024-Jan-03 07:08 AMPST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.