

FACILITY: ARSARA DIESEL TRUCK / S5708 INSP. TYPE: Complete INSP. START: 2025-Jul-16 04:00 PM PDT
INSPECTOR: SANDHU, SHAMSHER SINGH / 114059 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Jul-16 09:27 PM PDT
WORK ORDER #: Annual

VEHICLE JUR: British Columbia REGI: 13987010 VIN: 2M5931610M1191576
PLATE #: 36805K UNIT/FLEET#: V1005 OWNER/LESSEE NAME: CWB NATIONAL LEASING INC.
(LESSOR), TRANSHUB LOGISTICS LTD.
LICENCED GVW(kg): 0 BODY STYLE: Van Trailer ADDRESS: PO BOX 98057 SCOTTSDALE PO
VEHICLE YEAR: 2021 ODOMETER: Delta, British Columbia
MAKE: MANAC HUB ODOMETER: V4E3M9, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	34	13	7	8	16	
2	Clamp	30	Automatic	35	34	16	14	8	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	50	Lining (Shoe)	14	15	Drum		
2	40	65	Lining (Shoe)	17	13	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.


Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: SANDHU, SHAMSHER SINGH

Signature: 

This Inspection Report was submitted to CVSE on 2025-Jul-16 09:28 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSED014

7/16/2025 9:28:07 PM PDT

Commercial Vehicle
Inspection ReportDecal Number: GK34387
Decal Expiry Date: 2026-Jul-31
Inspection Number: 21428349

Inspection Result:

PASS

FACILITY:	ARSARA DIESEL TRUCK / S5708	INSP. TYPE:	Complete	INSP. START:	2025-Jul-16 04:00 PM PDT
INSPECTOR:	SANDHU, SHAMSHER SINGH / 114059	INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2025-Jul-16 09:27 PM PDT
WORK ORDER #:		INSP. REASON:	Annual		
VEHICLE JUR:	British Columbia	REGI:	13987010	VIN:	2M5931610M1191576
PLATE #:	36805K	UNIT/FLEET#:	V1005	OWNER/LESSEE NAME:	CWB NATIONAL LEASING INC. (LESSOR), TRANSHUB LOGISTICS LTD.
LICENCED GVW(kg): 0		BODY STYLE:	Van Trailer	ADDRESS:	PO BOX 98057 SCOTTSDALE PO Delta, British Columbia V4E3M9, Canada
VEHICLE YEAR:	2021	ODOMETER:			
MAKE:	MANAC	HUB ODOMETER:			
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	34
2	Clamp	30	Automatic	35	34

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
13	7	8	16	
16	14	8	10	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	50
2	40	65

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	17	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Inspector: SANDHU, SHAMSHER SINGH

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-16 09:28 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/16/2025 9:28:07 PM PDT