



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GC82536
Decal Expiry Date: 2025-May-31
Inspection Number: 20944013

Inspection Result:

PASS

513-4

FACILITY: MODERN DIESEL TRUCK REPAIR LTD. / S15400 INSP. TYPE: Complete INSP. START: 2024-May-25 06:00 PM PDT
INSPECTOR: Aujla, Gagandeep / 300544 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2024-May-25 08:00 PM PDT
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 13988183 VIN: 2M5921615K1179603
PLATE #: 36808K UNIT/FLEET#: V1006 OWNER/LESSEE NAME: TRANSHUB LOGISTICS LTD.,
LICENCED GVW(kg): 0 BODY STYLE: Van Trailer ADDRESS: PO BOX 98057 SCOTTSDALE PO
VEHICLE YEAR: 2019 ODOMETER: Delta, British Columbia
MAKE: MANAC HUB ODOMETER: V4E3M9, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) MARKER LIGHT NOT WORKING REPAIR SAME DAY
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	36	36
2	Clamp	30	Automatic	36	36

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.9	11.9	11.9	12.7	
11.1	11.9	11.9	11.9	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	58	55
2	50	50

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	18	18
Lining (Shoe)	19	19

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: Aujla, Gagandeep Signature:

This Inspection Report was submitted to CVSE on 2024-May-25 10:04 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/25/2024 10:04:32 PM PDT