

## Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number: GK14721 2026-Jun-30 21397643

Inspection Result:

FACILITY:

ARSARA DIESEL TRUCK / S5708

INSP. TYPE: INSP. CLASS:

INSP. START:

OWNER/LESSEE NAME:

2025-Jun-18 05:00 PM PDT

INSPECTOR:

SANDHU, SHAMSHER SINGH /

Class 3 - Trailer and Semi-Trailer

WORK ORDER #:

114059

INSP. REASON:

Annual

INSP. COMPLETE:

2025-Jun-20 10:21 AM PDT

VEHICLE JUR:

VEHICLE YEAR:

British Columbia

REGI: UNIT/FLEET#:

13988183 V1006

VIN:

2M5921615K1179603

TRANSHUB LOGISTICS LTD. TRANSHUB LOGISTICS LTD.

LICENCED GVW(kg): 0

36806K

BODY STYLE ODOMETER:

Van Trailer

ADDRESS:

PO BOX 98057 SCOTTSDALE PO

Delta, British Columbia

V4C5Y4, Canada

MAKE. MODEL:

PLATE #:

2019 MANAC

HUB ODOMETER:

**BRAKE TYPE:** Air

**FUEL TYPE:** 

Vehicle Identification (VIN) Passed

Section 1 - Power Train Section 2 - Suspension Not Applicable Passed

1XL 2XL BOTH AIR BAG REPLACED, 2XL L/S SHOCK REPLACED

Section 3 - Brake System Section 3A - Air Brakes

Section 3H - Hydraulic Brakes Section 4 - Steering

Section 5 - Instruments and Auxiliary

Not Applicable Not Applicable

Passed Passed

Not Applicable

Not Applicable

R/S TOP LIGHT FIX

Equipment

Comment:

Comment

Inspector:

Section 6 - Lamps

Section 7 - Electrical System

Section 8 - Frame and Body Passed Passed Section 9A - Tires Passed Section 9B - Wheels Section 10 - Coupling Devices Passed

Section 11 - Other Vehicle Components

Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Type Size Slack Adj. Left Right Axles 30 Automatic 34 35 Clamp 2 Clamp 30 Automatic 36 34

Inner R Outer R Outer L Inner L 12 9 9 11 6 10 10 10 Comment:

Air Brake Camshaft Rotation (degrees) Axles Left

Right 65 40

Brake Lining/Pad (mm) Lining/Pad Lining (Shoe) Lining (Shoe) Comment:

Left Right 13 17 18

Tire Tread Depth (mm)

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Left

Rotor Thickness or Drum Inside Diameter (mm)

R stor/Drum

Drum

Inspection Comments:

1

2

Has this Vehicle been road tested? SANDHU, SHAMSHER SINGH Road Test Date

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-20 10:22 AM PDT

70

35

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

Steering

Right

