



**BRITISH
COLUMBIA**

Commercial Vehicle Inspection Report

Decal Number: GJ71556
Decal Expiry Date: 2025-Dec-31
Inspection Number: 21388885

Inspection Result:

PASS

313-6

FACILITY:	GOLDEN TRUCK REPAIR LTD. / S6948	INSP. TYPE:	Complete	INSP. START:	2025-Jun-12 11:00 AM PDT
INSPECTOR:	SINGH, UPKAR / 109969	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jun-12 01:00 PM PDT
WORK ORDER #:		INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11674252	VIN:	3AKJGLD5XGSGX9324
PLATE #:	92641P	UNIT/FLEET#:	TH120	OWNER/LESSEE NAME:	TRANSHUB LOGISTICS LTD, TRANSHUB LOGISTICS LTD
LICENCED GVW(kg):	47000	BODY STYLE:	Truck Tractor	ADDRESS:	27-5858 132ST
VEHICLE YEAR:	2016	ODOMETER:	890550 Miles		Surrey, British Columbia
MAKE:	FREIGHTLIN	HUB ODOMETER:			V3X1N1, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	38	40
2	Clamp	30L	Automatic	48	52
3	Clamp	30L	Automatic	52	48

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	11.75			11.3	✓
	10.32	10.35	10.75	10.16	
	8.85	8.5	11.69	11.15	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	70	70
2	65	55
3	30	30

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	14	15
Lining (Shoe)	15	15
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: SINGH, UPKAR

Signature: _____

This Inspection Report was submitted to CVSE on 2025-Jun-12 03:56 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQ/VP at the Commercial Vehicle Safety Enforcement

CVSED014

6/12/2025 3:56:12 PM PDT