

A203



Commercial Vehicle Inspection Report

Decal Number: GK36959
Decal Expiry Date: 2026-Oct-31
Inspection Number: 21837581

Inspection Result:
PASS

FACILITY: AWA MOBILE TRUCK AND TRAILER / S17194 INSP. TYPE: Complete INSP. START: 2025-Oct-20 11:51 AM PST
INSPECTOR: Kostur, Roman Joseph / 203530 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Oct-20 01:52 PM PST
WORK ORDER #:

VEHICLE JUR: British Columbia REGI: 07075707 VIN: 2DE1BFZ3351017737
PLATE #: 11732K UNIT/FLEET#: A203 OWNER/LESSEE NAME: Essential Transport Inc, ESS
LICENCED GVW(kg): 999999 BODY STYLE: Flat Deck Trailer ADDRESS: 6-1718 Byland Rd
VEHICLE YEAR: 2005 ODOMETER: West Kelowna, British Columbia
MAKE: DOEPKER HUB ODOMETER: VIZ 1A9, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) #3 axle broken not broken spring
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) Weld rear corners of deck weld up right side tender
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) Adjust fifth wheel to much play
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	31.7	31.7	13	13	13	13	
2	Clamp	30	Automatic	31.7	31.7	12	11	14	14	
3	Clamp	30	Automatic	31.7	31.7	13	13	14	14	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	25	25	Lining (Shoe)	19	19	Drum	419.20	419.20
2	53	45	Lining (Shoe)	19	19	Drum	420.80	420.10
3	25	48	Lining (Shoe)	19	19	Drum	419.20	420.20

Comment:

Comment:

Comment:

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:
Inspector: Kostur, Roman Joseph Signature:

This Inspection Report was submitted to CVSE on 2025-Oct-21 08:54 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION
The personal information collected on this form is collected under the authority of section 218 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations, it is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulatory matters, in-vehicle inspections, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSICVP at the Commercial Vehicle Safety Enforcement, CVSE0014.

10/21/2025 8:58:10 AM PST