



# Commercial Vehicle Inspection Report

Decal Number: GK36984  
 Decal Expiry Date: 2027-Mar-31  
 Inspection Number: 21690884

B220

Inspection Result:  
**PASS**

**FACILITY:** AWA MOBILE TRUCK AND TRAILER / S17194  
**INSR. TYPE:** Complete  
**INSR. START:** 2026-Mar-10 08:38 AM PDT  
**INSR. CLASS:** Class 3 - Trailer and Semi-Trailer  
**INSR. COMPLETE:** 2026-Mar-10 10:38 AM PDT  
**INSPECTOR:** Kostur, Roman Joseph / 203530  
**INSR. REASON:** Annual  
**WORK ORDER #:**

**VEHICLE JUR:** British Columbia  
**REGI:** 08624930  
**VIN:** 2T9FA282591011175  
**PLATE #:** 19981K  
**UNIT/FLEET#:** B220  
**OWNER/LESSEE NAME:** Essential Transport Inc, ESS  
**LICENCED GWV(kg):** 999999  
**BODY STYLE:** Flat Deck Trailer  
**ADDRESS:** 6-1718 Byland Rd  
**VEHICLE YEAR:** 2009  
**ODOMETER:**  
 West Kelowna, British Columbia  
**MAKE:** THRWAY  
**HUB ODOMETER:** V1Z1A9, Canada  
**MODEL:**  
**BRAKE TYPE:** Air  
**FUEL TYPE:**

<b>Vehicle Identification (VIN)</b>	Passed
<b>Section 1 - Power Train</b>	Not Applicable
<b>Section 2 - Suspension</b>	Passed
<b>Section 3 - Brake System</b>	Repaired (same day) Replaced number 2 left broken slack adjuster replaced #1 right shoes and drum
<b>Section 3A - Air Brakes</b>	Repaired (same day) Replaced #1 right brake pot broken spring #2 left brake pot broken spring
<b>Section 3H - Hydraulic Brakes</b>	Not Applicable
<b>Section 4 - Steering</b>	Not Applicable
<b>Section 5 - Instruments and Auxiliary Equipment</b>	Passed
<b>Section 6 - Lamps</b>	Passed
<b>Section 7 - Electrical System</b>	Passed
<b>Section 8 - Frame and Body</b>	Repaired (same day) Weld cracks
<b>Section 9A - Tires</b>	Passed
<b>Section 9B - Wheels</b>	Passed
<b>Section 10 - Coupling Devices</b>	Passed
<b>Section 11 - Other Vehicle Components</b>	Not Applicable

Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Wheels	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	34	8	8	11	7	
2	Clamp	30	Automatic	34	34	10	12	10	11	

Comment: \_\_\_\_\_

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right	
1	64	25	Lining (Shoe)	17	21	Drum	421.00	419.00	
2	46	28	Lining (Shoe)	18	19	Drum	421.90	419.90	

Comment: \_\_\_\_\_

**Inspection Comments:**  
 Has this vehicle been road tested?  No **Road Test Date:** \_\_\_\_\_ **Road Tester:** \_\_\_\_\_  
**Inspector:** Kostur, Roman Joseph **Signature:** RK

This Inspection Report was submitted to CVSE on 2026-Mar-10 10:39 AM PDT  
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

**KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION**  
 Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection report for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.  
 VSD0014  
 10/2020 10:40 17 AM PDT