



# Commercial Vehicle Inspection Report

Decal Number: GH36633  
Decal Expiry Date: 2026-Apr-30  
Inspection Number: 21325270

108-14  
Inspection Result:  
**PASS**


**FACILITY:** RAPID TRUCK AND TRAILER REPAIR / S12291  
**INSPECTOR:** MASSIGA, KOFFI / 112833  
**WORK ORDER #:**  
**INSP. TYPE:** Complete  
**INSP. CLASS:** Class 2 - Heavy Vehicle with LGVW 5501 kg or more  
**INSP. REASON:** Annual  
**INSP. START:** 2025-Apr-23 11:00 AM PDT  
**INSP. COMPLETE:** 2025-Apr-23 01:00 PM PDT

**VEHICLE JUR:** British Columbia  
**PLATE #:** VD0767  
**LICENCED GVW(kg):** 14000  
**VEHICLE YEAR:** 2005  
**MAKE:** INTERNATNA  
**MODEL:**  
**REGI:** 02535078  
**UNIT/FLEET#:** 2051  
**BODY STYLE:** Van  
**ODOMETER:** 283726 KM  
**HUB ODOMETER:** 283726 KM  
**BRAKE TYPE:** Hydraulic  
**FUEL TYPE:** Diesel  
**VIN:** 1HTMPAFM65H682875  
**OWNER/LESSEE NAME:** KENO TRUCKING LTD, KENO TRUCKING LTD.  
**ADDRESS:** 8623 GRANVILLE ST SUITE 190  
Vancouver, British Columbia  
V6P5A2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) CHECK THE BRAKES
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Tire Tread Depth (mm)						Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Outer L	Inner L	Inner R	Outer R	Steering	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	10			9	✓	Pad	16	16	Rotor	39.50	39.60
2	10	10	11	12		Pad	15	15	Rotor	39.70	39.50

**Comment:**

**Inspection Comments:**  
Has this Vehicle been road tested? No  
**Inspector:** MASSIGA, KOFFI  
**Road Test Date:**  
**Signature:**   
**Road Tester:**

This Inspection Report was submitted to CVSE on 2025-Apr-25 01:27 PMPDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.