



BRITISH
COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: GH36405
Decal Expiry Date: 2025-Jul-31
Inspection Number: 21207549

Top-8
Inspection Result:
PASS

FACILITY:	RAPID TRUCK AND TRAILER REPAIR / S12291	INSP. TYPE:	Complete	INSP. START:	2025-Jan-13 12:00 PM PST
INSPECTOR:	MASSIGA, KOFFI / 112833	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jan-13 02:00 PM PST
WORK ORDER #:		INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	14403377	VIN:	1XKYDP0X5HJ987704
PLATE #:	VF9066	UNIT/FLEET#:		OWNER/LESSEE NAME:	KENO TRUCKING LTD, KENO TRUCKING LTD
LICENCED GVW(kg):	39500	BODY STYLE:	Truck Tractor	ADDRESS:	8623 GRANVILLE STREET Vancouver, British Columbia V6P5A2, Canada
VEHICLE YEAR:	2017	ODOMETER:	1351037 KM		
MAKE:	KENWORTH	HUB ODOMETER:	1351037 KM		
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Repaired (same day)	REPLACE FRONT DIFF SEAL
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	CHECK ALL THE BRAKES
Section 3A - Air Brakes	Repaired (same day)	REPLACE NUMBER 2 AXLE BRAKES, AND DRUMS ON BOTH SIDES
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Repaired (same day)	LICENSE PLATE REPLACED
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Repaired (same day)	REPLACE GLAN HAND SEAL
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24L	Automatic	25	25	6.1			8.5	✓
2	Clamp	30L	Automatic	25	25	10.9	10.9	13.3	11.7	
3	Clamp	30L	Automatic	25	25	10.9	10.9	10.9	10.9	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)

Brake Lining/Pad (mm)

Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	35	Lining (Shoe)	18	18	Drum	0.00	0.00
2	20	18	Lining (Shoe)	21	21	Drum	419.20	419.20
3	35	35	Lining (Shoe)	19	19	Drum	0.00	0.00

Comment:

Comment:

Comment: DID NOT REMOVE #1, AND #3 BRAKES AND DRUMS

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: MASSIGA, KOFFI

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-16 10:23 AM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQV/P at the Commercial Vehicle Safety Enforcement

CVSE0014

1/16/2025 10:23:50 AM PST