



**BRITISH  
COLUMBIA**

# Commercial Vehicle Inspection Report

Decal Number: GF20859  
Decal Expiry Date: 2025-Oct-31  
Inspection Number: 21303318

Inspection Result:

**PASS**

T13-3

<b>FACILITY:</b>	GOLDEN TRUCK REPAIR LTD. / S6948	<b>INSP. TYPE:</b>	Complete	<b>INSP. START:</b>	2025-Apr-07 10:00 AM PDT
<b>INSPECTOR:</b>	SINGH, UPKAR / 109969	<b>INSP. CLASS:</b>	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	<b>INSP. COMPLETE:</b>	2025-Apr-07 11:30 AM PDT
<b>WORK ORDER #:</b>		<b>INSP. REASON:</b>	Semi-annual		

---

<b>VEHICLE JUR:</b>	British Columbia	<b>REGI:</b>	14448941	<b>VIN:</b>	3AKJGEDR5HDHY8603
<b>PLATE #:</b>	WD0914	<b>UNIT/FLEET#:</b>	TH205	<b>OWNER/LESSEE NAME:</b>	1062278 B C LTD, 1062278 B C LTD
<b>LICENCED GVW(kg):</b>	39000	<b>BODY STYLE:</b>	Truck Tractor	<b>ADDRESS:</b>	5858 132 ST
<b>VEHICLE YEAR:</b>	2017	<b>ODOMETER:</b>	450488 Miles		Surrey, British Columbia
<b>MAKE:</b>	FREIGHTLIN	<b>HUB ODOMETER:</b>			V3X1N1, Canada
<b>MODEL:</b>		<b>BRAKE TYPE:</b>	Air		
		<b>FUEL TYPE:</b>	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24L	Automatic	38	38
2	Clamp	30L	Automatic	48	50
3	Clamp	30L	Automatic	52	52

Comment:

## Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
9.52			9.22	✓
14.65	16.4	14.75	16.53	
7.35	7.65	6.1	6.51	

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	40	40
3	30	35

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	16
Lining (Shoe)	17	16
Lining (Shoe)	16	17

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	420.65	420.37
Drum	420.11	420.00
Drum	420.00	420.25

Comment:

## Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Road Tester:

Inspector: SINGH, UPKAR

Signature: \_\_\_\_\_

This Inspection Report was submitted to CVSE on 2025-Apr-07 03:27 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

CVSED014

4/7/2025 3:27:51 PM PDT