



Commercial Vehicle Inspection Report

Decal Number: GK36029
Decal Expiry Date: 2026-Mar-31
Inspection Number: 21498298

Inspection Result:

PASS

FACILITY: GEMM DIESEL LTD. / S3195 INSP. TYPE: Complete INSP. START: 2025-Sep-16 08:54 AM PDT
INSPECTOR: Botrokoff, Sturlin / 300656 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW INSP. COMPLETE: 2025-Sep-16 10:54 AM PDT
WORK ORDER #: W79333 INSP. REASON: Semi-annual

VEHICLE JUR: Saskatchewan REGI: VIN: 4VND1GHE6YN789162
PLATE #: UNIT/FLEET#: OWNER/LESSEE NAME:
LICENCED GVW(kg): 46500 BODY STYLE: Tractor ADDRESS:
VEHICLE YEAR: 2000 ODOMETER: 257657 KM
MAKE: VOLVO HUB ODOMETER:
MODEL: BRAKE TYPE: Air
FUEL TYPE: Diesel

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) #3 AXLE BRAKES CHANGED, #2L BRAKE CHANGED.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Repaired (same day) STEERING U-JOINT CHANGED.
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	24	Automatic	40	35
2	Clamp	30	Automatic	45	45
3	Clamp	30	Automatic	45	30

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
12			12	✓
20	21	20	21	
21	19	20	20	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	45
2	30	90
3	30	30

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	17
Lining (Shoe)	17	12
Lining (Shoe)	17	17

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: Botrokoff, Sturlin

Road Test Date:

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-16 10:54 AM PDT.
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014

9/16/2025 10:54:29 AM PDT